Note: This document has not been finalised. LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

To: AIG Asia Pacific Insurance Pte. Ltd. From: LKK Auto Consultants Pte Ltd 51 Ubi Ave 1 #01-25

AIG Building, 78 Shenton Way #09-16

Paya Ubi Industrial Park Singapore 408933 Singapore 079120

Attn: Toh, Yuslinda Date: 14 Jan 2025

Preliminary Advice

Vehicle No : SNE898J Accident Date : 13/07/2024 Make : AUDI Q3 Policy No. : 7210150861 **Assignment Date** : 15/07/2024 Excess : S\$0.00 Date of Inspection : 18/07/2024 Est. Duration of Repair : 5

Inspection At : PREMIUM AUTOMOBILES PTE LTD (UBI)

> 55 UBI ROAD 1 SINGAPORE 408699

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	40,301.00 (inclusive supp \$99.00)
Devised Assessed	.C¢	4C 404 FC

Revised Amount :S\$ 16,134.56 Check Items (Estimated) :S\$ 0.00 Total :S\$ 16,134.56

:S\$ Lump Sum Repair

Total Loss Consideration

New for Old Value :S\$

Pre-Accident Value :S\$ 160,000.00 COE / PARF Rebate :S\$ 85,533.00

Salvage Value :S\$

Margin for Repair :S\$ 74,467.00

Remarks

(X)	The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindl
		let us have your authorisation.

The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.

Other comments: Kindly approve on supplementary. (x)