

Main Office:

Mova Building
No. 22, Jalan Kilang,
Singapore 159419
Tel : (65) 6476 3333
Fax : (65) 6271 5891
www.mova.com.sg

Workshop Dept:

Block 1008,
Bukit Merah Lane 3,
#01-04/06/08/94
Singapore 159722

Tel : (65) 6272 3892
Fax : (65) 6270 8314
Co. Reg. 198904033G
GST Reg. M2-0088864-2

ESTIMATE

11/7/2024

INDIA INT'L INSURANCE PTE LTD
64 CECIL STREET
#04-06 IOB BUILDING
SINGAPORE 049711.

Vehicle No: SMH7804E
Vehicle Model: H/SHUTTLE
Est No: CBMQ24070135
Claims ref:
Accident Date: 08/07/24
In Charge: KEONG
Remarks:

No	Description	Qty	U. Price	Amounts S\$
LIST ITEMS:				
1	REAR BOOT EMBLEM "SHUTTLE "	1 PC	\$ 96.30	\$ 96.30
2	REAR BUMPER	1 PC	\$ 748.60	\$ 748.60
3	REAR BOOT (REPAIR)	1 PC		\$ -
	LIST TOTAL S\$			\$ 844.90
	20% DISCOUNT S\$			\$ (168.98)
				<u>\$ 675.92</u>
SPECIAL NET ITEMS:				
1	REAR BUMPER SENSOR	1 PC	200.00	\$ 200.00
	SPECIAL NET TOTAL S\$			<u>\$ 200.00</u>
LABOUR CHARGE:				
1	TO REPAIR REAR END PANEL, REAR BOOT, REMOVE & REFIX DAMAGED PARTS, STRAIGHTEN & REALIGN AFFECTED AREAS			\$ 400.00
2	TO SPRAY REAR BOOT, END PANEL, REAR BUMPER, REVERSE SENSOR & AFFECTED AREAS			\$ 550.00
	TOTAL LABOUR COST S\$			<u>\$ 950.00</u>
AMOUNT S\$				\$ 1,825.92
GST @ 9%				\$ 164.33
AMOUNT DUE S\$				<u>\$ 1,990.25</u>
Customer's Signature		MOVA AUTOMOTIVE PTE LTD		