

2020 SPRAY PAINTING PTE LTD
8 KAKI BUKIT AVE 4
#03-19 PREMIER @KAKI BUKIT
SINGAPORE 415875

TO	: CHINA TAIPING	DATE : 17/07/2024
VEHICLE NO	: SJM3722T (2007)	Hui Rong
VEHICLE MODEL	: TOYOTA CAMRY	
CHASSIS NO	: MR053BK4107013853	

QTY	DESCRIPTION	CONDITION	REPAIRER'S ESTIMATE(\$\$)	SURVEYOR ADJUSTMENT
	<u>PARTS (LIST ITEMS)</u>			
1	REAR BUMPER Deformed		685.10	✓
2	REAR BUMPER SIDE HOLDER @65.60 Not new		131.20	X
3	REAR BUMPER REFLECTOR @83.20 Lt cracked		166.40	83.20
4	REAR BUMPER REINFORCEMENT Dented		531.20	✓
5	REAR END PANEL Repair		698.60	X
6	REAR END PANEL TOP GARNISH Deformed		382.20	✓
7	TAILLAMP @558.30 Lt cracked		1116.60	558.30
8	TAILLAMP PANEL @241.50 Not new		483.00	X
9	BOOTLID Dented		1086.50	✓
10	BOOTLID LOCK Rnd		408.90	✓
11	BOOTLID WEATHERSTRIPE Not new		231.40	X
12	BOOTLID HINGE @82.80 Not new		165.60	X
13	BOOTLID INNER TRIM Not new		381.40	X
14	BOOTLID OUTER GARNISH Not new		381.50	X
15	BOOTLID REFLECTOR @380.80 Not new		761.60	X
16	TOYOTA LOGO		61.70	✓
17	CAMRY WORDING } New		65.10	✓
18	2.0 EMBLEM		61.10	✓
19	SPARE TYRE PANEL TOP COVER Not new		289.90	X
			8089.00	
		Less 25%	2022.25	25%
			6066.75	
	<u>SPECIAL NETT ITEMS</u>			
1	REAR NUMBER PLATE } Not new		30.00	X
2	REAR NUMBER PLATE HOLDER		30.00	X
3	REAR BUMPER CLIPS Not new		50.00	30
4	REAR END PANEL TOP GARNISH CLIPS Not new		20.00	✓
5	REAR END PANEL SEALANT Not new		60.00	X
6	BOOTLID INNER TRIM CLIPS Not new		30.00	X
7	BOOTLID OUTER GARNISH CLIPS Not new		30.00	X
8	REVERSE SENSOR Dented		280.00	20

3923.30
2942.47

250

S/N	DESCRIPTION	REPAIRER'S ESTIMATE (S\$)	SURVEYOR ASSESSMENT (S\$)
	<u>LABOUR</u>		
1	PANEL BEATING	1200.00	500
2	SPRAY PAINTING	1200.00	600
3	WIRING	50.00	30
4	TO APPLY TUFF COAT	150.00	30
5	TO REMOVE UPHOLSTERY	150.00	30
6	TO TRANSFER BOOTLID FITTINGS	150.00	60
7	TO REMOVE REVERSE SENSOR	100.00	50
	Labour Total :	3010.00	
	TOTAL (PARTS & LABOUR):	9596.75	

1300

total: 4492.47

L/s 3.6K

04 Days.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer: *[Signature]*

Signature: *[Signature]*

Date: 27/11/2027

SPRAY PAINTING PTE. LTD.
UEN: 202008876K