

CARSMITH PRIVATE LIMITED

PREMIER@8KAKI BUKIT AVE 4 #04-35 SINGAPORE415875

Tel: 9091 0000/ Email: info@carsmith.biz

VEHICLE NO: SNB7328H

MAKE & MODEL: TOYOTA COROLLA

DOA: 13.07.2024

CLAIM TYPE: TP CLAIM

not Authorized
Mr
Morris
16/7/24
1/5 \$2500/
take ph. Hk rep-
3 days.

ESTIMATION QUOTE

PARTS	QTY	PRICE (\$)	REMARKS
FRONT DOOR LH	1	\$ 1,554.00	Bodywork
FRONT DOOR INNER LOCK LH	1	\$ 511.92	11 X
FRONT DOOR INNER LOCK LATCH LH	1	\$ 117.84	11 X
FRONT DOOR CHECK/ARRESTOR LH	1	\$ 156.00	11 X
FRONT DOOR HINGE	2	\$ 231.12	11 X
FRONT DOOR OUTER KEY LOCK LH	1	\$ 260.04	11 X
FRONT DOOR OUTER HANDLE LH	1	\$ 95.52	11 X
FRONT DOOR OUTER HANDLE INNER SEAL LH	1	\$ 46.44	11 X
FRONT DOOR OUTER MOULDING LH	1	\$ 193.68	11 X
FRONT DOOR WEATHERSTRIP LH	1	\$ 189.36	11 X
FRONT DOOR POWER WINDOW MASTER LH	1	\$ 482.28	8u X
FRONT DOOR POWER WINDOW MOTOR SWITCH LH	1	\$ 433.33	11 X
FRONT DOOR REGULATOR GEAR LH	1	\$ 158.16	11 X
FRONT DOOR WINDOW GLASS	1	\$ 475.00	11 X
REAR DOOR LH	1	\$ 1,489.70	R X
REAR DOOR INNER LOCK LH	1	\$ 511.92	11 X
REAR DOOR INNER LOCK LATCH LH	1	\$ 117.84	11 X
REAR DOOR CHECK/ARRESTOR LH	1	\$ 156.00	11 X
REAR DOOR OUTER KEY LOCK LH	1	\$ 260.04	11 X
REAR DOOR HINGE LH	2	\$ 231.12	11 X
REAR DOOR OUTER MOULDING LH	1	\$ 193.68	11 X
REAR DOOR WEATHERSTRIP LH	1	\$ 189.36	11 X
REAR DOOR OUTER HANDLE LH	1	\$ 95.52	11 X
REAR DOOR OUTER HANDLE INNER SEAL LH	1	\$ 46.44	11 X
REAR DOOR WINDOW GLASS	1	\$ 375.00	11 X
SIDE ROCKER PANEL COVER	1	\$ 652.00	11 X
REAR BUMPER	1	\$ 1,976.50	11 X
REAR BUMPER RETAINER LH	1	\$ 114.20	11 X
REAR BUMPER BRACKET LH	1	\$ 101.40	11 X
REAR FENDER LH	1	\$ 1,857.00	R X
REAR FENDER LH Rocker panel garnish LH	1	\$ 998.40	cut/Toon
TAILLAMP BRACKET LH	1	\$ 225.00	11 X

\$ 14,495.81

LESS 25% \$ 3,623.95

SUB TOTAL \$ 10,871.86

SPECIAL NETT ITEMS	QTY	PRICE (\$)	REMARKS
FRONT NUMBER PLATE	1	\$ 90.00	11 X
FRONT BUMPER CLIP	1 SET	\$ 50.00	11 X
FRONT PANEL TOP GARNISH CLIP	1 SET	\$ 50.00	11 X
JOINT SEALANT	1	\$ 100.00	11 X

SUB TOTAL \$ 290.00

LABOUR	QTY	PRICE (\$)	REMARKS
CHECK ALL WIRING AND LIGHTING SYSTEM	1	\$ 240.00	20
REMOVE AND RENEW REAR REVERSE SENSOR	1	\$ 120.00	11X
REMOVE AND REFIT FRONT AND REAR LINING, TRIM AND GARNISH	1	\$ 300.00	11X
PANEL BEATING ON AFFECTED AREAS AND RENEW DAMAGE PARTS	1	\$ 1,200.00	400
SPRAY PAINTING ON AFFECTED AREAS	1	\$ 1,200.00	800
APPLY ANTI RUST ON AFFECTED AREAS	1	\$ 150.00	30

SUB TOTAL \$ 3,210.00

GRAND TOTAL \$ 14,371.86

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

P- 2552.40
 252
 1914.30
 1250
 3164.30
 202
 2531.