

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315 Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliate data Fadamatian Intermetianala Dag Francuta Fra Automatalia					
Affiliated to Federation Internationale Des Experts En Automobile					
MS	INCOME INSURAN		Ref:	CS/INC24070268/Avh3e2	
	75 BRAS BASAH R	OAD SINGAPORE 189557	Date:	24/10/2024	
	THOOME CENTRE	511.67 II 61.12 166667	Code:	INC	
1.	1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SLS 3364M	Veh. Inspected	SNN 1649H	
	Policy No.	-	Coverage	0	
	Claim No.	MT/1286457-001	Excess	\$0.00	
	Assign From	LIM SERENE	Assign Date	16/07/2024	
2. Vehicle Details					
	Make & Model	TOYOTA ALPHARD	C.C	2493	
	Engine No.	2ARH633396	Year of Reg.	29/06/2016	
	Chassis No.	AGH300040358	Colour	GREY	
	Odometer	135328 KM	Steering	IN ORDER	
	Brakes	IN ORDER	General	GOOD	
	Modification(s)	RIMS: SPORTS RIM			
3. Conditions of Tyres					
		Size	Make	Balance (mm)	
	R/H Front Tyre	255/40 R20	MICHELIN	6	
	L/H Front Tyre	255/40 R20	MICHELIN	6	
	R/H Rear Tyre	255/40 R20	MICHELIN	6	
	L/H Rear Tyre	255/40 R20	MICHELIN	6	
4. Description of Damages					
THE VEHICLE SUSTAINED DAMAGES AT THE N/S BODY.					
DAMAGES SEE DETAILS.					
5. General Information					
	Accident Date	13/07/2024	Inspection Date	16/07/2024 (16:03)	
	Survey held at	t HD PERFECT AUTOWORK PTE LTD 8 KAKI BUKIT AVENUE 4, #08-09, PREMIER @ KAKI BUKIT, SINGAPORE 415875			
5a. Remarks					
A) THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.					
5b.		Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR: 7 Working Days					