

Company Reg No: 202136905K

Tel : 6341 6789 Fax: 6341 6778
E-mail:jlperfectautowork@gmail.com



DATE : 12.07.2024

TO	: INCOME MOTOR CLAIMS DEPTS
VEHICLE NO	: SLQ9219X
MODEL	: VOLVO V40 T2
DATE OF ACCIDENT	: 08.07.2024
TIME OF ACCIDENT	: 11:05 HOURS

Veron.

WE APPEND HEREUNDER THE ESTIMATED COST OF REPAIRS TO BE CARRIED OUT TO THE ABOVE VEHICLE.

CLAIM DETAIL : PARTS

CLAIM DETAIL : PARTS				
S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	REAR FENDER RH <i>Derfio</i>	1	\$ 1,985.00	\$ 1,985.00
2	REAR FENDER GLASS C/W MOULDING RH <i>New</i>	1	\$ 400.00	\$ 400.00
3	REAR FENDER AIR VENT RH <i>New</i>	1	\$ 138.00	\$ 138.00
4	REAR FENDER AIR VENT PANEL RH <i>New</i>	1	\$ 572.00	\$ 572.00
5	REAR FENDER INNER COWLING RH <i>torn</i>	1	\$ 385.00	\$ 385.00
6	REAR ABS SENSOR <i>2</i>	1	\$ 153.00	\$ 153.00
7	REAR SHOCK ABSORBER RH <i>HP</i>	1	\$ 475.00	\$ 475.00
8	REAR LOWER ARM RH <i>m</i>	1	\$ 578.00	\$ 578.00
9	REAR KNUCKLE ARM RH	1	\$ 760.00	\$ 760.00
10	REAR WHEEL HUB WITH BEARING RH <i>2</i>	1	\$ 465.00	\$ 465.00
11	REAR UPPER ARM RH <i>HP</i>	1	\$ 250.00	\$ 250.00
12	REAR ADJUSTABLE ARM RH <i>m</i>	1	\$ 189.00	\$ 189.00
13	REAR CONTROL ARM RH	1	\$ 238.00	\$ 238.00
14	REAR LINKAGE	1	\$ 210.00	\$ 210.00
15	REAR BUMPER <i>torn</i>	1	\$ 1,684.00	\$ 1,684.00
16	REAR BUMPER INNER SIDE GARNISH RH <i>New</i>	1	\$ 286.00	\$ 286.00
17	REAR BUMPER SIDE RETAINER <i>New</i>	2	\$ 74.00	\$ 148.00
18	REAR BUMPER BRACKET <i>New</i>	2	\$ 65.00	\$ 130.00
19	REVERSE SENSOR RH <i>2</i>	1	\$ 408.00	\$ 408.00
20	REVERSE SENSOR HOLDER <i>HP</i>	6	\$ 64.00	\$ 384.00
21	TAILLAMP RH <i>HP</i>	1	\$ 736.00	\$ 736.00

TO : **INCOME** MOTOR CLAIMS DEPTS
 VEHICLE NO : **SLQ9219X**
 MODEL : **VOLVO V40 T2**
 DATE OF ACCIDENT : 08.07.2024
 TIME OF ACCIDENT : 11:05 HOURS

TOTAL PRICE \$ 10,574.00
 LESS 10% \$ 1,057.40
SUB TOTAL PRICE \$ 9,516.60

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT
1	SIDE SKIRT CLIP RH <i>new</i>	1	\$ 60.00	\$ 60.00
2	REAR FENDER SEALANT RH <i>new</i>	1	\$ 80.00	\$ 80.00
3	REAR FENDER TOP GARNISH CLIP (SET) <i>new</i>	1	\$ 40.00	\$ 40.00
4	REAR FENDER COWLING CLIP (SET) <i>new</i>	1	\$ 80.00	\$ 80.00
5	REAR FENDER INNER TRIM CLIPS (SET) <i>new</i>	1	\$ 80.00	\$ 80.00
6	REAR FENDER GLASS SEALANT RH <i>new</i>	1	\$ 100.00	\$ 100.00
7	TAILLAMP CLIP (SET) <i>new</i>	1	\$ 50.00	\$ 50.00
8	REAR BUMPER CLIP (SET) <i>new</i>	1	\$ 150.00	\$ 150.00
9	REAR WHEEL SPORT RIM <i>new</i>	1	\$ 1,800.00	\$ 1,800.00
10	REAR WHEEL TYRE <i>new</i>	1	\$ 480.00	\$ 480.00
11	BRAKE OIL <i>new</i>	1	\$ 80.00	\$ 80.00

TOTAL \$ 3,050.00

CLAIM DETAILS: LABOUR AND SPRAY PAINTING (REAR)

S/N	JOB DESCRIPTION	PRICE	ADJUSTED COST
1	PANEL BEATING, REMOVAL AND REPLACING PARTS	\$ 1,800.00	600
2	TO SPRAY PAINT AFFECTED AREA	\$ 1,800.00	400
3	TUFF COAT	\$ 350.00	40
4	WIRING CHECK	\$ 380.00	30
5	REMOVE AND REFIX CUSHION SEAT/ UPHOLSTRY AND ROOF LINNING TO FACILITATE REPAIR	\$ 250.00	60
6	REMOVE AND REFIX REAR UNDERCARRIAGE	\$ 1,200.00	X
7	TO PRESS REAR WHEEL BEARING	\$ 80.00	X

TO : **INCOME** MOTOR CLAIMS DEPTS
VEHICLE NO : **SLQ9219X**
MODEL : **VOLVO V40 T2**
DATE OF ACCIDENT : 08.07.2024
TIME OF ACCIDENT : 11:05 HOURS

8	FOUR WHEEL ALIGNMNET	\$ 120.00	80
9	CONDUCT WATER LEAKAGE TEST	\$ 100.00	+
10	REMOVE AND REFIX REVERSE SENSOR AND DISTANCE SETTING	\$ 250.00	50
11	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT/CONTROL UNITS, RESET MEMORIES TO SPECIFICATION ETC.	\$ 550.00	150

1410

TOTAL \$ 6,880.00

TOTAL PARTS COST : \$ 12,566.60
TOTAL LABOUR COST : \$ 6,880.00
TOTAL REPAIR COST : \$ 19,446.60

Adrian L
L/S 16/07/24.
05 Days

NB: THIS IS ONLY AN ESTIMATE AND SHOULD ADDITIONAL WORK BE FOUND NECESSARY TO BE CARRIED OUT IN THE COURSE OF REPAIRS, EXTRA MATERIALS AND LABOUR COST WILL BE CHARGED ACCORDINGLY WHICH HOWEVER, YOU WILL BE INFORMED PRIOR TO ACTION TAKEN.

PARTS PRICES ARE SUBJECT TO CHANGES.

YOURS FAITHFULLY,

IRENE

SERVICE ADVISOR
IRENE
HP : 8297 9787

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Total: 5586.

L/S: 4450 ✓