

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315 Reg. No: 199607198R GST Reg. No. 19-9607198-R

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO GBB 7356T

	REPLACEMENT OF PARTS						
Qty	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)			
1	RH DOOR	BENT	\$1,386.00	\$1,386.00			
1	RH DOOR OUTER HANDLE	SERVICEABLE	\$333.00	\$0.00			
1	RH DOOR MUD FLAP	NOT NECESSARY	\$444.00	\$0.00			
1	RH DOOR MUD FLAP GARNISH	CRACKED	\$111.00	\$111.00			
1	RADIATOR SPARE TANK	DENTED	\$222.00	\$222.00			
1	REAR RH SIDE GATE	BENT	\$1,109.00	\$1,109.00			
1	REAR RH SIDE DOOR STOPPER	DENTED	\$42.00	\$42.00			
	LESS 10.00% DISCOUNT		(\$364.70)	(\$287.00)			
		\$3,282.30	\$2,583.00				

Special Nett						
Qty	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)		
1	BTE COOLANT (50%) (SN)	NECESSARY	\$30.60	\$17.00		
1	RH DOOR 'COMPANY ADDRESS' STICKER (SN)	NECESSARY	\$36.00	\$30.00		
1	REAR RH SIDE DOOR 'COMPANY ADDRESS' LOGO (SN)	NECESSARY	\$297.00	\$200.00		
		\$363.60	\$247.00			

Labour					
	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)	
	REMOVE & TRANSFER RH DOOR & NECESSARY ATTACHMENT SPARE PARTS ITEM }		\$0.00	\$0.00	
	REMOVE & TRANSFER REAR RH SIDE DOOR & NECESSARY ATTACHMENT SPARE PARTS ITEM }		\$0.00	\$0.00	
	REMOVE AND REFIT RH DOOR, RH DOOR OUTER HANDLE, RH DOOR MUD FLAP GARNISH, RADIATOR SPARE TANK, REAR RH SIDE DOOR, REAR RH SIDE DOOR STOPPER }		\$700.00	\$500.00	
	PUTTY / PRIMER APPLICATION, SPRAY PAINTING RH DOOR, REAR RH SIDE DOOR		\$800.00	\$600.00	
		\$1,500.00	\$1,100.00		
				<u> </u>	

GRAND TOTAL	\$5,145.90	\$3,930.00		
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)		\$3,050.00		
Report Ref No: CS/LIP24070275/Kqh3m4				

MARKET VALUE: \$5,000.00 (EST)-LTA REIMBURSEMENT VALUE: \$1,005.00=NETT VALUE: \$3,995.00



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315 Reg. No: 199607198R GST Reg. No. 19-9607198-R

KSC

KENNETH KONG SENG CHEONG

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of reposibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.