

Main Office:

Mova Building
No. 22, Jalan Kilang,
Singapore 159419
Tel: (65) 6476 3333
Fax: (65) 6271 5891
www.mova.com.sg

Workshop Dept:

Block 1008,
Bukit Merah Lane 3,
#01-04/06/08/94
Singapore 159722

Tel: (65) 6272 3892
Fax: (65) 6270 8314

Co. Reg. 198904033G
GST Reg. M2-0088864-2

ESTIMATE

13/7/2024

CHINA TAIPING INSURANCE SINGAPORE PTE LTD

3 ANSON ROAD

#16-00 SPRINGLEAF TOWER

SINGAPORE 079909

Vehicle No: SLH3658Z

Vehicle Model: V/W JETTA

Est No: CBMQ24070146

Claims ref:

Accident Date: 12/07/24

In Charge: KEONG/E

Remarks:

No	Description	Qty	U. Price	Amounts S\$
----	-------------	-----	----------	-------------

LIST ITEMS:

1	REAR BOOT <i>h/</i>	1	PC \$ 1,875.50	\$ 1,875.50 ✓
2	REAR BOOT LOGO <i>re</i>	1	PC \$ 175.00	\$ 175.00 ✓
3	REAR BOOT EMBLEM "JETTA" <i>re</i>	1	PC \$ 82.70	\$ 82.70 ✓
4	REAR BOOT EMBLEM "230" <i>re</i>	1	PC \$ 118.10	\$ 118.10 ✓
5	REAR BOOT EMBLEM "TSI" <i>re</i>	1	PC \$ 91.70	\$ 91.70 ✓
6	REAR BOOT LAMP RH <i>cm</i>	1	PC \$ 480.20	\$ 480.20 ✓
7	REAR BOOT NUMBER PLATE LAMP?	1	PC \$ 172.40	\$ 172.40 X
8	REAR BOOT DAMPLE RH X	1	PC \$ 236.60	\$ 236.60 X
9	REAR BOOT RUBBER X	1	PC \$ 323.85	\$ 323.85 X
10	TAILLAMP RH <i>cm</i>	1	PC \$ 490.80	\$ 490.80 ✓
11	TAILLAMP LOWER BRACKET RH <i>re</i>	1	PC \$ 110.10	\$ 110.10 ✓
12	TAILLAMP GROMMET <i>re</i>	1	PC \$ 15.00	\$ 15.00 ✓
13	REAR BUMPER <i>de</i>	1	PC \$ 1,866.40	\$ 1,866.40 ✓
14	REAR BUMPER LOWER GARNISH <i>cut</i>	1	PC \$ 696.70	\$ 696.70 ✓
15	REAR BUMPER REFLECTOR RH X	1	PC \$ 196.70	\$ 196.70 X
16	REAR BUMPER BRACKET RH	1	PC \$ 152.20	\$ 152.20 X
17	REAR BUMPER RETAINER RH	1	PC \$ 160.40	\$ 160.40 ✓
18	REAR BUMPER CLIPS <i>re</i>	10	PC \$ 3.50	\$ 35.00 ✓

LIST TOTAL S\$

10% DISCOUNT S\$

6197.60

619.76

5577.84

180.00

SPECIAL NET ITEMS:

1	REAR BUMPER SENSOR ?	1	PC \$ 220.00	\$ 220.00 180 ✓
2	REAR NUMBER PLATE X	1	PC \$ 40.00	\$ 40.00 X

SPECIAL NET TOTAL S\$

\$ 7067.84

\$ 260.00

LS \$ 5650

6 days

Main Office:
Mova Building
No. 22, Jalan Kilang,
Singapore 159419
Tel: (65) 6476 3333
Fax: (65) 6271 5891
www.mova.com.sg

Workshop Dept:
Block 1008,
Bukit Merah Lane 3,
#01-04/06/08/94
Singapore 159722
Tel: (65) 6272 3892
Fax: (65) 6270 8314
Co. Reg. 198904033G
GST Reg. M2-0088864-2

ESTIMATE

13/7/2024

CHINA TAIPING INSURANCE SINGAPORE PTE LTD
3 ANSON ROAD
#16-00 SPRINGLEAF TOWER
SINGAPORE 079909

Vehicle No: SLH3658Z
Vehicle Model: V/W JETTA
Est No: CBMQ24070146
Claims ref:
Accident Date: 12/07/24
In Charge: KEONG
Remarks:

No	Description	Qty	U. Price	Amounts S\$
LABOUR CHARGE:				
1	TO CUT & WELD REAR END PANEL, TO REPAIR REAR END PANEL, REAR FENDER RH, FLOOR PANEL, TO REMOVA & REFIX DAMAGED PARTS, STRAIGHTEN & REALIGN AFFECTED AREAS			\$ 840.00 600
2	TO SPRAY AFFECTED AREAS, REAR FENDER L+R, REAR END PANEL REAR FLOOR PANEL, REAR BUMPER, REVERSE SENSOR & AFFECTED AREAS			\$ 850.00 600
3	TO REMOVE & REFIX LUGGAGE COMPARTMENT, SIDE COVER, SIDE GARNISH & AFFECTED AREAS			\$ 80.00 40
4	TO INSTALL REVERSE SENSOR & CHECK WATER SEEPAGE			\$ 60.00 40
5	TO RUST PROOF AFFECTED AREAS			\$ 50.00 30
TOTAL LABOUR COST S\$				\$ 1,880.00

AMOUNT S\$ \$ 8,691.42
GST @ 9% \$ 782.23
AMOUNT DUE S\$ \$ 9,473.64

Customer's Signature

MOVA AUTOMOTIVE PTE LTD

Paul
#90010068
6 days
4/5
12/08/24
Regr after repair