

1ST AUTOMOTIVE SERVICES PTE LTD

Address: 53 Ubi Ave 1 #01-23 S(408934)
Contact: 83686767

Estimate for XD5840D(Mitsubishi Fuso FV51J)

Not Authorized
New
Moras
22/7/24
2/555000
4 days

- *FRONT RH DOOR
- *FRONT RH DOOR OUTER GARNISH
- *FRONT DOOR SIGNAL LAMP RH
- *FRONT BUMPER
- *FRONT BUMPER CENTER GARNISH RH
- *FRONT BUMPER RH FOGLAMP
- *FRONT BUMPER RH FOGLAMP COVER
- *FRONT BUMPER SIDE GARNISH RH
- *FRONT BUMPER TOP GARNISH (BLACK)
- *FRONT RH CORNER GARNISH SIGNAL LAMP
- *FRONT RH HEADLAMP
- *FRONT RH HEADLAMP BRACKET
- *FRONT RH HEADLAMP COVER
- *FRONT RH STEP GARNISH (LOWER)
- *FRONT RH STEP GARNISH (LOWER) STEEL PLATE
- *FRONT RH STEP GARNISH (TOP)
- *FRONT RH STEP GARNISH (TOP) STEEL PLATE
- *FRONT RH STEP GARNISH BRACKET (FRONT)
- *FRONT RH STEP GARNISH BRACKET (REAR)
- *FRONT RH CORNER GARNISH
- *FRONT RH CORNER GARNISH BRACKET

R	\$6,995.60	X
RS	\$880.40	X
520/mis	\$231.60	✓
DOS	\$1,993.87	✓
17	\$295.51	X
17	\$299.34	X
17	\$197.25	✓
Dig	\$190.84	✓
17	\$98.41	X
17	\$227.91	X
17	\$1,389.44	X
17	\$935.64	X
190-84	17	\$305.00 ✓
320	\$795.63	✓
320	\$366.60	✓
17	\$355.27	✓
R	\$326.60	X
17	\$971.96	X
480.00	17	\$699.25 ✓
17/17	\$1,251.09	✓
17	\$150.80	X
	\$18,958.01	
	\$4,739.50	
	\$14,218.51	

Less 25%

TO REMOVE, REINSTALL ELCTRICAL WIRING HARNESS, CHECK LIGHTING AND RESETTNG HEADLAMP FOCUSSING (TO FR)

\$100.00 20

TO RESPRAY PAINTING ON THE CHANGE BODYPARTS, REPAIR PORTION, AND WHERE CONSISTENT TO THE ACCIDENT

\$1,500.00 800

TO PROVIDE LABOUR, WORKMANSHIP TO CHANGE THE ABOVE DAMAGED BODYPARTS, REPAIR, RE-CONSTRUCT AND RE-ALIGN BODY STRUCTURE, BODY ALIGNMENTS AND DAMAGED CONSISTENT TO THE ACCIDENT

\$2,000.00 900

TO APPLY ANTI-RUST CHEMICAL ON REPAIRED AND REPLACED PANEL

17 \$150.00 X

APPLY ANTI RUST CHEMICAL TRANSFER TO DOOR

17 \$200.00 X

17 \$200.00 X

\$4,150.00

\$18,368.51

TOTAL

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

2-605299
252
4539.74
1720
6259.74
202
507