



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933
TEL: 6256 3561 FAX: 6256 4315
Reg. No: 199607198R GST Reg. No.
19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile					
MS CHINA TAIPING INSURANCE (S) PTE LTD 3 ANSON ROAD #16-00 SPRINGLEAF TOWER SINGAPORE 079909		Ref: Date: Code:	CD/CTI24070302/Kua3 18/07/2024 CTI		
1. Policy Particulars :- DIRECT SETTLEMENT					
	Insured Veh.	SJA 707X	Veh. Inspected	SHD 5176C	
	Policy No.	-	Coverage	0	
	Claim No.	-	Excess	\$0.00	
	Assign From	-	Assign Date	18/07/2024	
2. Vehicle Details					
	Make & Model	TOYOTA PRIUS 5DR HATCHBACK (AUTO)		C.C	1798
	Engine No.	2ZR2B91590		Year of Reg.	19/12/2018
	Chassis No.	JTDKB3FU203078485		Colour	METALLIC PEARL WHITE/RED
	Odometer	614242 KM		Steering	IN ORDER
	Brakes	IN ORDER		General	GOOD
	Modification(s)	RIMS: STANDARD ALLOY RIM			
3. Conditions of Tyres					
		Size	Make	Balance (mm)	
	R/H Front Tyre	195/65R15	WANLI	8	
	L/H Front Tyre	195/65R15	WANLI	8	
	R/H Rear Tyre	195/65R15	WANLI	8	
	L/H Rear Tyre	195/65R15	WANLI	8	
4. Description of Damages					
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.					
DAMAGES SEE DETAILS.					
5. General Information					
	Accident Date	14/07/2024	Inspection Date	16/07/2024	
	Survey held at	TRANS-CAB AUTO SERVICES PTE LTD NO.2 ANG MO KIO ST 63 SINGAPORE 569111			
5a. Remarks					
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.					
5b. Estimate Days of Repair					
ESTIMATED NORMAL PERIOD FOR REPAIR: 2.5 Working Days					