

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/0561/2024/KS
DATE : 19-Jul-24
WIP : 23956

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 24/07/2024.

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Motor Claims Dept

Hi Adrian,

4 Days + 1 Sun - OK - Allan Boo

15-Aug-24

OWNER'S NAME : MR.WONG JUN MING (HUANG JUNMING)
ADDRESS : 70 SHENTON WAY
#31-07
SINGAPORE 079118
TELEPHONE : HP +65 97854683
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO : 7210081351-02
VEHICLE NO : **SNA 9896 B**
MODEL CODE : A4 2.0 TFSI S TRONIC
MODEL YEAR : 27/7/2021
ENGINE NO : DEM 028960
CHASSIS NO : WAUZZZF47MA025311
MILEAGE : KM
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 4-Jul-24
PLACE OF ACCIDENT : LEFT TURN SLIPROAD, AFTER CTE EXIT TO YIO CHU KANG
TOWARDS THOMSON ROAD

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SNA 9896 B.

S/N	NATURE OF JOBS		ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHT, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER.	S/N \$	480.00	\$ 480.00
2	TO REMOVE AND TRANSFER BOTH HEADLIGHT CONTROL UNIT AND POWER MODULE.	S/N \$	700.00	\$ 250.00
3	TO DISMANTLE AND RENEW FRONT BUMPER, BONNET AND BOTH HEADLIGHT. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$	2,100.00	\$ 1,000.00
4	TO RESPRAY FRONT BUMPER AND BONNET.	\$	2,000.00	\$ 1,100.00
5	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$	292.00	\$ 292.00
TOTAL LABOUR CHARGES		: \$	5,572.00	\$ 3,122.00

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO.SNA 9896 B.

			DAMAGED PARTS & PRICES		
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS	
1	FRONT BUMPER	1	\$ 2,670.00	\$	2,136.00
2	FRONT BUMPER FIXING PARTS	1	\$ 420.00		
3	FRONT BUMPER SECURING STRIP	2	\$ 90.00		
4	FRONT BUMPER GRILLE - CENTER	1	\$ 245.00		
5	FRONT BUMPER CLOSING ELEMENT - LOWER CENTRE	1	\$ 329.00		
6	FRONT BUMPER AIR GUIDE - LH / RH	2	\$ 176.00		
7	FRONT BUMPER CLOSING ELEMENT - UPPER CENTRE	1	\$ 329.00	\$	262.80
8	FRONT BUMPER AIG GUIDE GRILLE - LH / RH	2	\$ 338.00		
9	RADIATOR GRILLE	1	\$ 1,949.00	\$	1,559.20
10	"CAUTION" STICKER	1	\$ 25.00	\$	19.44
11	"A/C" STICKER	1	\$ 10.00	\$	7.52
12	FRONT BUMPER GUIDE SECTION - LH / RH	2	\$ 92.00		
13	FRONT BUMPER TOP BRACKET	1	\$ 173.00	\$	138.00
14	FRONT FOAM FILLER PIECE	1	\$ 237.00	\$	189.60
15	FRONT REINFORCEMENT BEAM	1	\$ 1,033.00	\$	826.40
16	FRONT BUMPER TOP BRACKET SUPPORT - LH / RH	2	\$ 74.00	\$	57.76
17	LED HEADLIGHT - LH / RH	2	\$ 18,408.00	\$	7,363.20
18	LED HEADLIGHT SPACER - LH / RJ	3	\$ 150.00		
19	LIFT CYLINDER - LH / RH	2	\$ 504.00		
20	LIFT CYLINDER BRACKET - LH / RH	2	\$ 16.00		
SUB TOTAL SPARE PARTS		:	\$ 27,268.00	\$	12,559.92

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SNA 9896 B.

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
				\$ 12,559.92
21	LIFT CYLINDER HOSE	1 \$	118.00	
22	HEADLIGHT TOP COVER - LH / RH	2 \$	110.00	\$ 43.44
23	BONNET	1 \$	3,470.00	\$ 2,776.00
24	BONNET ATTACHMENT PARTS	1 \$	460.00	
25	BONNET HINGE - LH / RH	2 \$	744.00	
26	BONNET IMPACT PROTECTION - CENTER	1 \$	36.00	\$ 28.40
27	BONNET IMPACT PROTECTION - LH / RH	2 \$	70.00	\$ 56.80
28	BONNET STRIKER - LH / RH	2 \$	126.00	
29	BONNET LID LOCK - LH / RH	2 \$	491.00	
30	BONNET BOWDEN CABLE - CENTER	1 \$	71.00	
31	BONNET BOWDEN CABLE	1 \$	71.00	
32	FRONT NO PLATE	S/N \$	60.00	\$ 60.00
	ADD PARTS - SUPPLEMENTARY			\$ 151.60
33	SUNDRIES	\$	600.00	\$ 30.16
TOTAL SPARE PARTS			\$ 33,695.00	\$ 15,706.32
TOTAL LABOUR CHARGES			\$ 5,572.00	\$ 3,122.00
GRAND TOTAL			\$ 39,267.00	\$ 18,828.32

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APROVED
 SPARE PARTS ARE SPECIAL NETT.



PREMIUM AUTOMOBILES

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg



Supplementary Estimate

GST Reg No. 19-9902271-W

AIG Asia Pacific Insurance Pte Ltd 78 Shenton Way #07-16 AIG Building Singapore 079120 Attn: Motor Claims Dept Tel: 6841 0055 / Fax: 6256 4315		Estimate No. Date Service Advisor Pages Regn No Model No	PA/OD/0561/2024/KS 2-Aug-24 GLORY 1 of 1 SNA 9896 B A4 2.0 TFSI S TRONIC
Quantity	Description	Unit Price	Amount
<u>Parts</u>			
1	FRONT BUMPER TOP COVER	\$ 160.00	\$ 127.60
2	OUTER TEMPERATURE SENSOR BRACKET	\$ 30.00	\$ 24.00
GRAND TOTAL		\$ 190.00	\$ 151.60

For Premium Automobiles Pte Ltd

Authorised Signature

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME :
SURVEYED DATE :
AUTHORISED DATE :
EXCESS COST :
LIABILITY :
REMARKS :

PLEASE NOTE : THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY.
FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT