

Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
GST:201001158E RCB NO:201001158E

SKT9466U
TP/AIG

M/S : AIG ASIA PACIFIC INSURANCE PTE LTD
78 SHENTON WAY
#07-16 AIG BUILDING
SINGAPORE 079120

TEL: 64193000

FAX: 64153727

ATTN: Motor Claim Department

Estimate No: ES2400674/YISHUN

Date: 14 Aug 2024

Policy No: MZD04027

Veh Reg No: SKT9466U

Make/Model: MAZDA MAZDA3 4-DOOR SEDAN 1.5L SP.6EAT

WS Ref: TP/AIG

Claim Type: Third Party

Accident Date: 13/07/2024

TP Veh Reg No: GBG9428E

Chassis No: JM6BM42A8G0309952

Engine No: P520281337

Reg. Date: 26/06/2015

Estimate Repair Cost to Vehicle No :SKT9466U

Description	U/Price	Quantity	List Price	Amount
			S\$	S\$
List Price				
1 REAR BUMPER	998.00	1 PC	998.00	✓
2 REAR BUMPER REINFORCEMENT	576.00	1 PC	576.00	✓
3 REAR BUMPER RH TOW HOOK COVER	18.80	1 PC	18.80	✓
4 REAR BUMPER CLIP	3.50	6 PC	21.00	✓
5 REAR BOOT INNER LOCK	124.00	1 PC	124.00	✓
6 REAR BOOT INNER RUBBER	140.00	1 PC	140.00	✓
			1,877.80	
		Less 20%	375.56	1,502.24
Special Net				
7 REVERSE SENSOR	200.00	1 SET	200.00	✓
			200.00	200.00
Labour				
8 REMOVE & REFIX REAR BUMPER ASSY;TO KNOCKING & REPAIR REAR END PANEL & REALIGN THE SAME	480.00	1 LA	480.00	200/300 ✓
9 PUTTY & RESPRAY ON REAR BUMPER,REAR PANEL,REAR REINFORCEMENT	480.00	1 LA	480.00	200/360 ✓
			960.00	960.00
			Total	S\$ 2,662.24
			Add GST @ 9%	239.60
			Total Amount Payable	S\$ 2,901.84

1613.80
322.76
1291.04
200
600
2091.04

45 1650/

2 days

For Cheng Hoe Motor Pte Ltd

AUTHORISED SIGNATURE