

MODERN AUTOMOTIVE PTE LTD
BLK 3023A UBI ROAD 1 # 01-61
SINGAPORE 408717

Tel : 67484422 / 67454422 Fax : 6747- 6720 REG NO 200501102H

SPF ACCIDENT CLAIMS SECTION
 Logistic Supports Services Division
 Police Logistics Department
 Police Logistics Base
 1 Hemmant Road
 Singapore 438675
 Tel: 6842 8429

Quotation
 DATE : 24.07.2024
 VEH NO : SMD6706H
 MODEL : BMW 216i
 D O A : 15.07.2024
 YR REF : QX374T

Xiao Chen.

Attn : Motor Claim Dept (Pls arrange vehicle survey & check liability)

RE : ESTIMATE FOR ACCIDENT REPAIR SMD6706H (BMW 216I)

<u>Item</u>	<u>Description</u>	<u>Qty</u>	<u>Amt</u>
NO	LIST ITEMS		
1	Rear Bumper <i>behind</i>	1	1,292.00 ✓
2	Rear Bumper Side Holder <i>new</i>	2	170.00 +
3	Rear Bumper Centre Moulding <i>cut</i>	1	109.00 ✓
4	Rear Bumper Reinforcement <i>2</i>	1	589.00 +
5	Rear Bumper Reflector <i>2 new</i>	2	152.00 +
6	Rear Bumper Inner Frame <i>new</i>	2	370.00 +
7	Rear Bumper Hands Free Module <i>2 new</i>	1	586.00 +
8	Rear Bumper Hands Free Module Bracket <i>new</i>	1	219.00 +
9	Rear Bumper Towing Cover <i>new</i>	1	43.00 +
10	Rear Bumper Sensor <i>2 pieces damaged 2031</i>	4	1,060.00 <i>330</i>
11	Rear Bumper Sensor Holder <i>new</i>	4	100.00 <i>192945</i>
			\$ 4,690.00
Less 5%			(234.50)
			\$ 4,455.50
<u>S/NET ITEMS</u>			
1	Rear Bumper Clips <i>new</i>	1	\$ 50.00 <i>30</i>
			\$ 50.00
Total parts			\$ 4,505.50

LABOUR CHARGE

1	To knocking out rear portion & renew above parts	\$ 400.00 <i>200</i>
---	--	----------------------

RE : ESTIMATE FOR ACCIDENT REPAIR SMD6706H (BMW 216I)

2	To putty & spray up paint works	\$	400.00	300
3	To check wiring	\$	50.00	x
4	To remove remove sensor	\$	100.00	50
5	To perform diagnostic test	\$	200.00	x
Total Labour		\$	1,150.00	
Grand Total		\$	5,655.50	

GST Will be reflected in the final bills

NOTE : -

PLEASE INFORM US WITHIN 14 DAYS, FROM THE DATE OF THIS LETTER, IN THE EVENT THAT THE OWNER/DRIVER IS IN BREACH OF ITS POLICY WITH YOUR COMPANY, FAILING WHICH WE SHALL HOLD YOUR COMPANY LIABLE FOR ALL COSTS OF REPAIRS, LOSS OF USE AND STORAGE.

total: 2509.45
y/s: 2K.
02 Days.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: