

Not Withheld
L/Sy @ 900/h

AAD2407-076

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC5570C

Vehicle No.:

Chassis No.:

Co UEN:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration:

22 JUL 2024

SHC5570C

JTDKB3FU103083385

200303878K

TOYOTA

PRIUS

18/7/2024

SLG1059X/ III

30/8/2019

PART

- 1 COVER, FRONT BUMPER
- 1 ABSORBER, FRONT BUMPER ENERGY
- 1 REINFORCEMENT SUB-ASSY, FRONT BUMPER
- 1 FRONT BUMPER SIDE RETAINER RH
- 1 JAR ASSY, WINDSHIELD WASHER
- 1 UNIT ASSY, HEADLAMP, RH
- 1 LAMP ASSY, FOG, RH
- 1 FENDER SUB-ASSY, FRONT RH
- 1 LINER, FRONT FENDER, RH
- 1 FRONT FENDER EMBLEM RH
- 1 GRILLE SUB-ASSY, RADIATOR
- 1 GRILLE, RADIATOR, LOWER NO.1

LIST

\$	Bulena	653.31	✓
\$	CM	100.17	✓
\$	R	902.16	X
\$	DI	80.10	✓
\$	SL	276.15	X
\$	SL	3,325.56	X
\$	SL	1,200.78	X
\$	R	1,236.69	X
\$	SL	260.51	X
\$	na	68.88	X
\$	SL	436.38	X
\$	SL	214.41	X
TOTAL	\$	8,755.10	
25%	\$	2,188.77	
	\$	6,566.32	

Special Nett

- 1 FRT BUMPER CLIP
- 1 FRT BUMPER SIDE RETAINER CLIP
- 1 FENDER LINER CLIP

\$	na	65.00	65.00
\$	na	65.00	X
\$	na	75.00	X
TOTAL	\$	205.00	

TOTAL PARTS \$ 6,771.32

LABOUR

Trans-cab Auto Services Pte Ltd**AAD2407-**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC5570C

To Rust-Proofing and apply undercoat Of The Affected Areas.	\$	nn 250.00	X
Putty And Spray Painting Of The Affected Portion.	\$	1,800.00	2201
To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	nn 380.00	X
To Check Electrical Lighting Concerned.	\$	170.00	201
Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$	2,000.00	2001
To check steering geometry and computer wheel alignment	\$	nn 220.00	X
To transfer of front fender panel fittings, attachment and perform water seepage test.	\$	nn 170.00	X

TOTAL \$ 4,990.00**Over All Total \$ 11,761.32****(Lump Sum) Repair Days****7 Days****20 days**

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: