

J-MART MOTOR PTE LTD

Block 5, Defu Lane 10, #01-578
Defu Industrial Park C, Singapore 539186
Tel : 6343-0934 Fax : 6343-0921
Email : jmartauto@gmail.com
Registration NO: 201400246D
GST Reg. NO: 201400246D

16-Jul-24

Our ref : TP/5435/24

Kin Yan Agrotech Pte Ltd

RE : Estimate cost for vehicle no : GBL 4319T

1 pc	rear lh fender	Bent	nett	2066.58	\$	2,160.00	
1 pc	rear bumper	Rnt				+ 667.20	
1 pc	lh taillamp	for new				+ 542.00	
1 pc	rear lh hup cap	lost				✓ 136.20	
						3,505.40	
						less 10%	350.54
							3154.86
1 pc	rear lh tyre	lot	snett	2160	160	300.00	
1 pc	rear lh rim	new			+	300.00	
1 pc	rear lh fnder co logo	} new			1000	1,500.00	
1 pc	lh trailing door logo				1000	1,500.00	
					500	1,000.00	
					600	1,000.00	
Panel beating.					✓	30.00	
Spray painting.					60	120.00	
Wiring.						8,904.86	
Upholstery.						801.44	
						Plus 9% GST	9,706.30

SD : Nine thousand seven hundred six & cents thirty only.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Arhin
h/s 17/07/24
06 Days

total \$416.58
2/s: 4.3K

4.3K