



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,  
Singapore 408933  
TEL: 6256 3561 FAX: 6256 4315  
Reg. No: 199607198R GST Reg. No.  
19-9607198-R

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO SLG 5323G

REPLACEMENT OF PARTS				
Qty	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
1	REAR BUMPER	BROKEN	\$612.04	\$612.04
1	REAR BUMPER REFLECTOR	BROKEN	\$76.78	\$76.78
1	REAR BUMPER RETAINER	BROKEN	\$132.33	\$132.33
1	REAR BUMPER BRACKET	NOT NECESSARY	\$120.23	\$0.00
1	REAR BUMPER REINFORCEMENT	DENTED	\$439.45	\$439.45
1	END PANEL	TO REPAIR SEE LABOUR	\$737.00	\$0.00
1	END PANEL TOP GARNISH	NOT NECESSARY	\$266.09	\$0.00
	<b>LESS 25.00% DISCOUNT</b>		(\$595.98)	(\$315.15)
			<b>\$1,787.94</b>	<b>\$945.45</b>

Special Nett				
Qty	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
1	SET REAR BUMPER CLIP	NECESSARY	\$30.00	\$30.00
1	SET REVERSE SENSOR	BROKEN	\$200.00	\$200.00
			<b>\$230.00</b>	<b>\$230.00</b>

Labour				
	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
	CHECK WIRING AND LIGHTING SYSTEM		\$80.00	\$30.00
	REMOVE TRIMS & GARNISHES TO FACILITATE REPAIR		\$120.00	\$50.00
	REMOVE & REPLACE REVERSE SENSOR		\$120.00	\$30.00
	PANEL BEATING ON AFFECTED AREAS. INCLUSIVE OF THE REPAIR OF END PANEL		\$600.00	\$400.00
	SPRAY PAINTING ON AFFECTED AREAS		\$600.00	\$500.00
	APPLY ANTI-RUST ON AFFECTED AREAS		\$80.00	\$20.00
			<b>\$1,600.00</b>	<b>\$1,030.00</b>

<b>GRAND TOTAL</b>	<b>\$3,617.94</b>	<b>\$2,205.45</b>
--------------------	-------------------	-------------------

<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)</b>	<b>\$1,750.00</b>
---	-------------------

Report Ref No: CS/AGI24070333/Enc



## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,  
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315  
Reg. No: 199607198R GST Reg. No.  
19-9607198-R

# **CTY**

STEVE CHEN TSUE YEE

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.