

## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933  
TEL: 6256 3561 FAX: 6256 4315  
Reg. No: 199607198R GST Reg. No. 19-9607198-R

To: INDIA INTERNATIONAL INSURANCE PL  
64 CECIL STREET  
#05-02 IOB BUILDING SINGAPORE 049711

From: LKK Auto Consultants Pte Ltd  
51 Ubi Ave 1 #01-25  
Paya Ubi Industrial Park  
Singapore 408933

Attn: GABRIEL WEE

Date: 05/02/2025

### PRELIMINARY ADVICE

Vehicle No	GV 6444P	Accident Date	19/07/2024
Make	TOYOTA HIACE DX	CLAIM No.	MCV2024D0008531
Assignment Date	22/07/2024	Excess	-
Inspection Date	24/7/2024	Est. Duration of Repair	4

Inspected At: KT MOTORWERK

### Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Workshop Estimate Amount:	\$	13,041.45
Revised Estimate Amount:	\$	2,453.15
"Check" Items Amount		\$0.00
Total	\$	2,453.15

### **Total Loss Consideration**

Book Value	\$0.00
Market Value	\$0.00
COE / PARF Rebate	
Salvage Value	\$0.00
Margin for Repair	

### Remarks

- [ ] The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- [ ] The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- [ ] Other comments: Please note that the preliminary advice amount (Revised & Check Items) stated are subject to consistency check, part prices and labour cost.