

5b.

ESTIMATED NORMAL PERIOD FOR REPAIR: 4 Working Days

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315 Reg. No: 199607198R GST Reg. No. 19-9607198-R

		Affiliated to Federation Internation	nale Des Experts En	Automobile
MS	INCOME INSURANCE LTD 75 BRAS BASAH ROAD		Ref:	CS/INC24070343/Enh3e2
			Date:	02/08/2024
	INCOME CENTRE	SINGAPORE 189557	Code:	INC
1.	Policy Particulars :- THIRD PARTY CLAIM			
	Insured Veh.	SLT 2537H	Veh. Inspected	SMT 403L
	Policy No.	-	Coverage	0
	Claim No.	MT/1287379-001	Excess	\$0.00
	Assign From	AMANDA CHOOI	Assign Date	23/07/2024
2. Vehicle Details				
	Make & Model	TOYOTA PREVIA AERAS	C.C	2362
	Engine No.	2AZ1B14413	Year of Reg.	26/03/2020
	Chassis No.	JTEGD56M407173856	Colour	BLACK
	Odometer	225483 KM	Steering	IN ORDER
	Brakes	IN ORDER	General	GOOD
	Modification(s)	RIMS: SPORTS RIM		
3.	Conditions of Tyres			
		Size	Make	Balance (mm)
	R/H Front Tyre	215/55Z R17	GREENTRAC	5
	L/H Front Tyre	215/55Z R17	GREENTRAC	5
	R/H Rear Tyre	215/55Z R17	GREENTRAC	5
	L/H Rear Tyre	215/55Z R17	GREENTRAC	5
4.	Description of Damages			
ГНЕ	VEHICLE SUSTAIN	NED DAMAGES AT THE O/S BODY.		
DAM	IAGES SEE DETAIL	_S.		
5.		General Information		
	Accident Date	05/07/2024	Inspection Date	23/07/2024 (10:42)
	Survey held at	STRIDES PREMIER AUTOMOTIVE SERVICES PL - 23 CHANGI SOUTH AVE 2 SINGAPORE 486443		
5a.	Remarks			
		AS CONDUCTED ON A"WITHOUT PE O YOUR INSTRUCTIONS, WE HAVE I		REPAIRS.

Estimate Days of Repair