



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No.
19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MS INCOME INSURANCE LTD	Ref:	CS/INC24070343/Enh3e2
75 BRAS BASAH ROAD	Date:	07/08/2024
INCOME CENTRE SINGAPORE 189557	Code:	INC

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SLT 2537H	Veh. Inspected	SMT 403L
Policy No.	-	Coverage	0
Claim No.	MT/1287379-001	Excess	\$0.00
Assign From	AMANDA CHOOI	Assign Date	23/07/2024

2. Vehicle Details

Make & Model	TOYOTA PREVIA AERAS	C.C	2362
Engine No.	2AZ1B14413	Year of Reg.	26/03/2020
Chassis No.	JTEGD56M407173856	Colour	BLACK
Odometer	225483 KM	Steering	IN ORDER
Brakes	IN ORDER	General	GOOD
Modification(s)	RIMS: SPORTS RIM		

3. Conditions of Tyres

	Size	Make	Balance (mm)
R/H Front Tyre	215/55Z R17	GREENTRAC	5
L/H Front Tyre	215/55Z R17	GREENTRAC	5
R/H Rear Tyre	215/55Z R17	GREENTRAC	5
L/H Rear Tyre	215/55Z R17	GREENTRAC	5

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY.

DAMAGES SEE DETAILS.

5. General Information

Accident Date	05/07/2024	Inspection Date	23/07/2024 (10:42)
Survey held at	STRIDES PREMIER AUTOMOTIVE SERVICES PL - 23 CHANGI SOUTH AVE 2 SINGAPORE 486443		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: 4 Working Days