



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Preliminary Advice

To :Liberty Insurance Pte Ltd

DATE: 25/7/2024

AVS24/2284-SLB 5539C

Date of loss	21/7/2024
Date of appointment	24/7/2024
Date of survey	24/7/2024
Location of survey	DETAIL LAB

Vehicle Details:

Claim Type:	THIRD PARTY
Vehicle number	SLB 5539C
Make and Model	TOYOTA HARRIER
Vehiclet Type	MOTORCAR
Date of registration	13/4/2026
Vehicle Colour	WHITE
Market Value (estimated)	\$43,000.00
LTA Rebate	\$21,944.00
Nett Value	\$21,056.00

Proposed/Revised repair cost:

Workshop Estimate	\$15,295.00
Revised Estimate	\$2,928.00
"Check items (Estimated)	\$1,045.00
Total	\$3,973.00
Number of days of repair	5 days (est)

Remarks:

The vehicle sustained damages at the n/s rear portion
Damages Consistent.
The above survey was conducted on a 'Without Prejudice' basis.
Please note that the preliminary advise amount (Revised and check items) stated are subject to consistency check, part prices and labour cost .