

FALCON AIR AUTO SERVICES PTE LTD

Tel No. :

MS FIRST CAPITAL INSURANCE LIMITED
16 RAFFLES QUAY
#42-01 HONG LEONG BUILDING 048581

Attention : Motor Claim Department

Contact : 62222311 Fax No. : 62223547

Estimate : ES709565

Date : 31/07/2024

Vehicle Num. : SMN 7784Y

Make/Model : OPEL ASTRA

Chassis/Eng# :

Accident Date : 21/07/2024

Claim No. :

Reference :

Policy No. :

Not Authored
in
motor

2/8/24

1/5 = 6000

Temporarily up
5 days.

S/N	Quantity	Particular	Unit Price	Amount S\$
-----	----------	------------	------------	------------

LIST ITEMS :				
1.	1PC	REAR BUMPER	2250.00	3,450.00 ✓
2.	2PCS	REAR BUMPER SIDE RETAINER	75.00	150.00 1PC
3.	1PC	REAR BUMPER TOW COVER	60	95.00 ✓
4.	1PC	REAR BUMPER LOWER	850	1,100.00 ✓
5.	1PC	O/S REAR BUMPER REFLECTOR	60.00	165.00 ✓
6.	4PCS	REVERSE SENSOR	380.00	1,520.00 1PC
7.	1PC	REVERSE SENSOR WIRE		550.00 X
8.	1PC	TAILGATE LOGO EMBLEM		125.00 X
9.	1PC	TAILGATE TURBO EMBLEM		110.00 X
10.	1PC	TAILGATE ASTRA EMBLEM		110.00 X
11.	1PC	REAR END PANEL	980.00	1,200.00 ✓
12.	1PC	REAR END PANEL GARNISH		380.00 X
13.	1PC	O/S TAILLAMP	580.00	1,200.00 ✓
14.	1PC	O/S REAR FENDER INNER SHIELD	202.00	280.00 ✓
15.	1PC	REAR COMPARTMENT BOARD		650.00 X
16.	1PC	REAR bumper beam	970	1,350.00 ✓
List TotalS\$:				12,435.00
10.00% Discount S\$:				1,243.50
				11,191.50
SPECIAL NETT ITEMS :				
1.	1SET	O/S REAR FENDER INNER SHIELD CLIPS	11	50.00 X

CONTINUE / ...

FALCON AIR AUTO SERVICES PTE LTD

Tel No. :

MS FIRST CAPITAL INSURANCE LIMITED
16 RAFFLES QUAY
#42-01 HONG LEONG BUILDING 048581

Attention : Motor Claim Department

Contact : 62222311 Fax No. : 62223547

Estimate : ES709565

Date : 31/07/2024
Vehicle Num. : SMN 7784Y
Make/Model : OPEL ASTRA
Chassis/Eng# :
Accident Date : 21/07/2024
Claim No. :
Reference :
Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
2.	1SET	REAR BUMPER CLIP	50.00	50.00 ✓
3.	1SET	REAR BUMPER RIVET	50.00	50.00 x
4.	1PC	REAR COMPARTMENT INSULATOR RUBBER	280.00	280.00 x
5.	1PC	REAR NUMBER PLATE	50.00	50.00 30
6.	1PC	REAR NUMBER PLATE SEAL	50.00	50.00 22
Special Nett Total S\$:				530.00
LABOUR :				
TO CHECK LIGHT AND WIRING			50.00	50.00 20
ANTI-RUST			100.00	100.00 30
TO APPLY BODY SEALANT ON BODY JOINTS			100.00	100.00 x
TO BREAK SEAL AT LTA / RESEAL AT VICOM			120.00	120.00 50
INSTALL REVERSE SENSOR IN NEW BUMPER			80.00	80.00 30
TO DIAGNOSE AND CLEAR CODE			200.00	200.00 x
TO REMOVE/REFIT GARNISH AND TRIMS TO FACILITATE REPAIRS			120.00	120.00 80
TO CONDUCT CHASSIS ALIGNMENT			350.00	350.00 x
LABOUR/PANEL BEATING			1,400.00	1,400.00 800
SPRAY PAINTING				
1)BUMPER 2)TAILGATE 3)END PANEL 4)RH FENDER			1,400.00	1,400.00 800
5) REAR COMP PANEL				
Labour Total S\$:				3,920.00

E. & O.E.

Total S\$: 15,641.50

for FALCON AIR AUTO SERVICES PTE LTD

TAMPINES BRANCH

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

2,6227
102
560430
102
1810
751630
222
6213