



Supplementary

Estimate No. : **b1 70581**
Date Estimated : **22/07/2024**
Prepared By : **Yap Mee Key**

Page No. :

- ESTIMATE REPAIR FOR -

Ong Siew Khim
158 Westwood Avenue

Singapore 648449

- ACCOUNT - 135

China Taiping Insurance (S) Pte Ltd
3 Anson Road
#16-00 Springleaf Tower
Singapore 079909

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	M LEAGE
SDV7288C	WBA62EG0505X47925	27/10/2023	X1 sDrive16i	11092

DESCRIPTION	ORIGINAL PRICE	DISC. %	NETT
* To transfer lock mechanism from old to new trunk lid include conducting checks on new boot lid central locking system for proper function	531.00		531.00
** To supply Ceramic Coating (See MCA's email)	300.00		300.00

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
# BLIND RIVET NUT M6	3.15	6.00	0.00	18.90

SUPPLEMENTARY ITEMS

Total Labour :	831.00
Total Parts :	18.90
Total Labour & Parts (before GST) :	849.90