

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315 Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile					
MS	S UNITED OVERSEAS INSURANCE LTD		Ref:	CS/UOI24070381/Uqp3	
	146 ROBINSON ROAD		Date:	15/08/2024	
	#02-01 UOI BUILDI	NG SINGAPORE 068909	Code:	UOI2	
1.	Policy Particulars :- OWN DAMAGE CLAIM				
	Insured Veh.	-	Veh. Inspected	SKX 3586A	
	Policy No.	DHOM110159391706	Coverage	0	
	Claim No.	-	Excess	\$500.00	
	Assign From	-	Assign Date	24/07/2024	
2.	Vehicle Details				
	Make & Model	TOYOTA COROLLA ALTIS CLASSIC (A)	c.c	1598	
	Engine No.	1ZRY212757	Year of Reg.	08/12/2015	
	Chassis No.	MR053REH104539100	Colour	GREY	
	Odometer	150310 KM	Steering	IN ORDER	
	Brakes	IN ORDER	General	GOOD	
	Modification(s)	RIMS: SPORTS RIM			
3. Conditions of Tyres					
		Size	Make	Balance (mm)	
	R/H Front Tyre	205/55R16	YOKOHAMA	6	
	L/H Front Tyre	205/55R16	YOKOHAMA	6	
	R/H Rear Tyre	205/55R16	YOKOHAMA	6	
	L/H Rear Tyre	205/55R16	YOKOHAMA	6	
4.		Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION.					
DAMAGES SEE DETAILS.					
5.	5. General Information				
_	Accident Date	20/07/2024	Inspection Date	24/07/2024	
	Survey held at	Id at SME MOTOR PTE LTD - 1 KAKI BUKIT AVE 6 #02-15 (AUTOBAY @KAKI BUKIT) SINGAPORE 417883			
5a. Remarks					

Estimate Days of Repair

A) THE MARKET VALUE IS \$\$26,000.00 (EST. AVERAGE)

ESTIMATED NORMAL PERIOD FOR REPAIR: 5 Working Days

5b.

B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.