

MG SOLUTION PTE LTD

23 Kaki Bukit Avenue 4 #04-01 Vicom Inspection Centre Singapore 415933

Tel: 6243 1373 Fax: 6243 1376

Reg. No: 201427944N

Email: MG3SOLUTION@GMAIL.COM

ATTENTION:	MOTOR CLAIMS DEPARTMENT	<i>Xiao Chen.</i>
DATE:	21-05-24	
CLAIM TYPE:	T/P CLAIM	
TO:	INCOME	
VEHICLE DETAILS		
VEHICLE NO:	SNC2354J	<i>RV31000395</i>
MAKE & MODEL:	HONDA VEZEL	
CHASSIS NO:		
ACCIDENT DETAILS		
DATE:	21 May, 2024	
TIME:	1000HRS	
THIRD PARTY REQUESTOR:	JACK LI	

CLAIM DETAILS: PARTS

S/N:	DESCRIPTION	QTY:	UNIT LIST PRICE	TOTAL LIST PRICE
1	FRONT BUMPER <i>Distal d</i>	1	\$ 980.00	\$ 980.00
2	FRONT BUMPER SIDE RETAINER <i>New</i>	1	\$ 62.40	\$ 62.40
3	FRONT BUMPER LOWER SPOILER <i>ct</i>	1	\$ 520.00	\$ 520.00
4	FRONT BUMPER LOWER SPOILER GUARD <i>ct</i>	1	\$ 150.00	\$ 150.00
5	FORNT BUMPER TOWING COVER <i>new</i>	1	\$ 80.00	\$ 80.00
6	FRONT BUMPER LOWER GRILLE <i>could</i>	1	\$ 190.00	\$ 190.00
7	FRONT BUMPER REINFORCEMENT <i>Deled</i>	1	\$ 420.00	\$ 420.00
8	FRONT BUMPER DAYLIGHT <i>could</i>	1	\$ 580.00	\$ 580.00
9	FRONT BUMPER DAYLIGHT HOUSING <i>could</i>	1	\$ 90.00	\$ 90.00
10	FRONT BUMPER SENSOR <i>3 of</i>	2	\$ 320.00	\$ 640.00
11	FRONT BUMPER SENSOR O RING <i>for</i>	2	\$ 20.00	\$ 40.00
12	FRONT GRILLE ASSY <i>could</i>	1	\$ 1,055.30	\$ 1,055.30
13	HEADLAMP <i>could</i>	1	\$ 2,855.30	\$ 2,855.30
14	HEADLAMP LOWER BRACKET <i>could</i>	1	\$ 80.00	\$ 80.00
15	FRONT FENDER <i>Deled</i>	1	\$ 520.00	\$ 520.00
16	FRONT FENDER INNER COWLING <i>Deled</i>	1	\$ 190.00	\$ 190.00
17	FRONT FENDER WHEEL ARCH <i>Deled</i>	1	\$ 220.00	\$ 220.00
18	SUPPORT PANEL <i>New</i>	1	\$ 820.00	\$ 820.00
19	WASHER TANK <i>Deled</i>	1	\$ 250.00	\$ 250.00

TOTAL PRICE \$ 9,743.00

LESS 20% \$ 1,948.60

6746
5396.80

110

SUB TOTAL PRICE \$ 7,794.40

SPECIAL NETT ITEMS

S/N:	DESCRIPTION	QTY:	UNIT LIST PRICE	TOTAL LIST PRICE
1	FRONT BUMPER PLATE <i>Me nu</i>	1	\$ 50.00	\$ 50.00
2	FRONT BUMPER CLIPS(SET) <i>nu</i>	1	\$ 20.00	\$ 20.00
3	FRONT BUMPER LOWER SPOILER CLIPS(SET) <i>3 nu</i>	1	\$ 20.00	\$ 20.00
4	FRONT FENDER INNER COWLING CLIPS(SET) <i>1 nu</i>	1	\$ 22.00	\$ 22.00
5	FRONT FENDER WHEEL ARCH CLIPS(SET) <i>nu</i>	1	\$ 20.00	\$ 20.00
6	WHEEL RIM <i>400</i>	1	\$ 1,000.00	\$ 1,000.00
			TOTAL	\$ 1,132.00

CLAIM DETAILS: LABOUR AND SPRAY PAINTING (FRONT)

1	PANEL BEATING, REMOVAL AND REPLACING PARTS	1	\$ 1,200.00	\$ 1,200.00
2	TO SPRAY PAINT AFFECTED AREA	1	\$ 1,000.00	\$ 1,000.00
3	TUFF COAT	1	\$ 250.00	\$ 250.00
4	WIRING CHECK	1	\$ 100.00	\$ 100.00
5	REMOVE AND REFIX CUSHION SEAT/ UPHOLSTERY AND ROOF LINING TO FACILITATE REPAIR	1	\$ 250.00	\$ 250.00
6	REMOVE AND REFIX REVERSE SENSOR AND DISTANCE SETTING	1	\$ 100.00	\$ 100.00
7	WHEEL ALIGNMENT	1	\$ 100.00	\$ 100.00
			TOTAL	\$ 3,000.00

ESTIMATE REPORT

TOTAL PARTS COST	\$	8,926.40
TOTAL LABOUR COST	\$	3,000.00
TOTAL REPAIR COST	\$	11,926.40

APPROVED DETAILS:

SURVEYOR:

CONTACT NO.:

PART BY PART/LUMP SUM

NO. OF DAYS

- Auto Consultants* hence notify the Repairer of the following:
- To resurvey before/after spray painting
 - To display damaged part(s) during resurvey
 - Parts prices are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modification(s) is allowed
 - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Adrian Cj
L/S 10/06/24
05 Days

Total: 6878.80
L/S: 55K