

## Huey Yon (LKKAUTO)

---

**From:** Rasul (LKKAUTO)  
**Sent:** Monday, 15 July 2024 3:20 PM  
**To:** Allan Wu  
**Cc:** claims@premiumauto.com.sg; carrine.leong@premiumauto.com.sg; jiayee.yap@premiumauto.com.sg; 'Boo seng yak'; Huey Yon (LKKAUTO)  
**Subject:** Re: FINAL REVISION - SMJ3012P - TP ECICS - SURVEYED ON 13 JUNE 2024

Hi Allan,

We will be advising our principal a cost of repair P/P \$40,294.80 /- with 11 days of repair before GST, subject to their approval.

Best Regards,

**Rasul** | Assessor

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email: [Rasul@lkkauto.com](mailto:Rasul@lkkauto.com) | fax: 6841-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

*Save the Earth. Print only when necessary.*

---

**From:** Allan Wu <allan.wu@premiumauto.com.sg>  
**Sent:** Monday, 15 July 2024 12:01 pm  
**To:** Rasul (LKKAUTO) <Rasul@lkkauto.com>; SUR <sur@lkkauto.com>  
**Cc:** claims@premiumauto.com.sg <claims@premiumauto.com.sg>; carrine.leong@premiumauto.com.sg <carrine.leong@premiumauto.com.sg>; jiayee.yap@premiumauto.com.sg <jiayee.yap@premiumauto.com.sg>; 'Boo seng yak' <boojohnny@gmail.com>  
**Subject:** RE: FINAL REVISION - SMJ3012P - TP ECICS - SURVEYED ON 13 JUNE 2024

Apologies,

Have a typo error on the final repair cost.

Should be \$40,294.80 @ 11 Days plus 2 Sundays and 1 PH.

Thank you and regards

**Allan Wu**

Bodyworks Department

**Premium Automobiles Pte Ltd** (Reg No 199902271W)

281 Alexandra Road Singapore 159938

p. +65 6836 2223 f. +65 6841 1183

e. [allan.wu@premiumauto.com.sg](mailto:allan.wu@premiumauto.com.sg) w. [www.audi.com.sg](http://www.audi.com.sg)

**Audi Showroom, Audi Centre** 281 Alexandra Road Singapore 159938 p. +65 6836 2223



**Email Disclaimer**

This email, including any attachment, is confidential and may also be privileged.

If you have received it in error, please notify us immediately by reply email and then delete this message from your system.

Please do not copy it or use it for any purpose, or disclose its contents or any attachment to any other person. Thank you

---

**From:** Allan Wu [mailto:[allan.wu@premiumauto.com.sg](mailto:allan.wu@premiumauto.com.sg)]

**Sent:** Friday, 12 July 2024 12:30 pm

**To:** 'rasul@lkkauto.com' <[rasul@lkkauto.com](mailto:rasul@lkkauto.com)>; 'SUR' <[sur@lkkauto.com](mailto:sur@lkkauto.com)>

**Cc:** 'claims@premiumauto.com.sg' <[claims@premiumauto.com.sg](mailto:claims@premiumauto.com.sg)>; [carrine.leong@premiumauto.com.sg](mailto:carrine.leong@premiumauto.com.sg);

'[jiayee.yap@premiumauto.com.sg](mailto:jiayee.yap@premiumauto.com.sg)' <[jiayee.yap@premiumauto.com.sg](mailto:jiayee.yap@premiumauto.com.sg)>; 'Boo seng yak' <[boojohnny@gmail.com](mailto:boojohnny@gmail.com)>

**Subject:** FINAL REVISION - SMJ3012P - TP ECICS - SURVEYED ON 13 JUNE 2024

Hi Rasul,

Attached are the before paint pictures and final revised estimate.

Kindly confirm repair cost of \$240,294.80 @ 11 Days plus 2 Sundays and 1 PH.

Your early confirmation is appreciated.

Thank you and regards

**Allan Wu**

Bodyworks Department

**Premium Automobiles Pte Ltd** (Reg No 199902271W)

281 Alexandra Road Singapore 159938

**p.** +65 6836 2223 **f.** +65 6841 1183

**e.** [allan.wu@premiumauto.com.sg](mailto:allan.wu@premiumauto.com.sg) **w.** [www.audi.com.sg](http://www.audi.com.sg)

**Audi Showroom, Audi Centre** 281 Alexandra Road Singapore 159938 **p.** +65 6836 2223



**Email Disclaimer**

This email, including any attachment, is confidential and may also be privileged.

If you have received it in error, please notify us immediately by reply email and then delete this message from your system.

Please do not copy it or use it for any purpose, or disclose its contents or any attachment to any other person. Thank you