

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/TP/0464/2024/EQ
DATE : 12-Jun-24
WIP : 19112

VEHICLE IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 13/6/2024

YOUR INSURED VEH NO : SJL 1155 Z

ECICS LIMITED

10 EUNOS ROAD 8

#09-04A, SINGAPORE POST CENTRE

SINGAPORE 408600

Attn: Motor Claims Dept

OWNER'S NAME : MR WAN MING FENG (WEN MINGFENG)
ADDRESS : BLK 93B TELOK BLANGAH STREET 31
#14-179
SINGAPORE 102093
TELEPHONE : HP +65 96206081
TYPE OF CLAIM : THIRD PARTY CLAIM
POLICY NO : 2070051171-04
VEHICLE NO : **SMJ 3012 P**
MODEL CODE : AUDI A3 SPORTSBACK 1.0 TF
MODEL YEAR : 23/3/2020
ENGINE NO : CHZ C38944
CHASSIS NO : WAUZZZ8V6LA049703
MILEAGE : 71,357 KM
DATE IN : 11-Jun-24
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 11-Jun-24
PLACE OF ACCIDENT : JUNCTION OF LOWER DELTA ROAD AND ALEXANDRA ROAD

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SMJ 3012 P

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO TOW BACK THE VEHICLE FROM ACCIDENT SCENE.	S/N \$ 280.00	invoice
2	TO REMOVE AND RENEW AIRCON CONDENSER, RADIATOR AND ADDITIONAL RADIATOR, CHECK ELECTRICAL FANS AND CONTROL UNIT.	S/N \$ 1,800.00	
3	TO CARRY OUT VACUUM AND REGAS FOR R134.	S/N \$ 600.00	
4	TO REMOVE AND TRANSFER LHS WING MIRROR TO FACILITATE DOOR PAINTING.	S/N \$ 450.00	
5	TO DISMANTLE AND RENEW FRONT BUMPER, BONNET, LHS FRONT FENDER AND LHS HEADLIGHT. TO RENEW FRONT LOCK CARRIER AND ALIGN TO POSITION. TO CUT OUT AND WELD LHS FRONT FENDER SUPPORT. TO REPAIR LHS A-PILLAR, LHS FRONT FENDER AND LHS SILL PANEL. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	@900 x 7 \$ 10,800.00	6300 5850
6	TO RESPRAY FRONT BUMPER, BONNET, LHS FRONT FENDER, LHS FRONT DOOR, LHS A-PILLAR, LHS SILL PANEL AND LHS FRONT FENDER SUPPORT.	@900 x 6.5 + 200 plus \$ 6,300.00	6050
SUBTOTAL LABOUR CHARGES		\$ 20,230.00	15480

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAJ@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SMJ 3012 P

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
7	TO REMOVE AND REINSTALL FRONT SUSPENSION. INSPECT FOR DAMAGES AND RENEW ACCORDINGLY.	S/N \$ 3,600.00	7X11
8	TO CARRY OUT COMPUTERISED WHEEL ALIGNMENT.	S/N \$ 280.00	/
9	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$ 480.00	/
TOTAL LABOUR CHARGES		: \$ 24,590.00	760

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMJ 3012 P

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
1	FRONT BUMPER <i>tom</i> ✓	1	\$ 2,411.00	✓
2	FRONT BUMPER FIXING PARTS <i>Xm</i>	1	\$ 209.00	X
3	FRONT BUMPER GUIDE SECTION - LH <i>ms</i> ✓	1	\$ 49.00	48.20
4	FRONT BUMPER GRILLE - CENTER <i>cm</i> ✓	1	\$ 201.00	✓
5	FRONT BUMPER CLOSING ELEMENT - LOWER CENTRE <i>?cm</i> ✓	1	\$ 373.00	✓
6	FRONT BUMPER CLOSING ELEMENT - LH <i>ms</i> ✓	1	\$ 357.00	✓
7	RADIATOR GRILLE <i>cm</i> ✓	1	\$ 1,784.00	✓
8	RADIATOR GRILLE CLOSING ELEMENT <i>cm</i> ✓	1	\$ 235.00	234.50
9	CAUTION SIGN STICKER <i>nu</i> ✓	1	\$ 25.00	24.30
10	AIR CONDITIONER STICKER <i>nu</i> ✓	1	\$ 10.00	9.40
11	FRONT BUMPER AIR GUIDE GRILLE - LH <i>cm</i> ✓	1	\$ 236.00	235.50
12	FRONT BUMPER REINFORCEMENT BEAM COVER <i>?cm</i> ✓	1	\$ 153.00	✓
13	FRONT BUMPER FOAM FILLER PIECE <i>cm</i> ✓	1	\$ 237.00	✓
14	FRONT BUMPER SIDE REINFORCEMENT BEAM <i>st</i> ✓	1	\$ 1,055.00	✓
15	OUTSIDE TEMPERATURE SENSOR BRACKET <i>nu</i> ✓	1	\$ 30.00	✓
16	HEADLIGHT - LH <i>bro</i> ✓	1	\$ 6,647.00	✓
17	HEADLIGHT POWER MODULE - LH <i>? short</i> ✓	1	\$ 904.00	903.50
18	HEADLIGHT CONTROL UNIT <i>? short</i> ✓	1	\$ 664.00	663.50
19	HEADLIGHT HEAT SINK - LH <i>? short</i> ✓	1	\$ 924.00	923.50
20	LIFT CYLINDER - LH <i>cm</i> ✓	1	\$ 170.00	✓
SUB TOTAL SPARE PARTS		:	\$ 16,674.00	<i>16460.40</i>

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMJ 3012 P

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
21	LIFT CYLINDER HOSE ? cut /	1	\$ 86.00	85.10
22	BONNET bt /	1	\$ 3,418.00	/
23	BONNET ATTACHMENT PARTS Xnn	1	\$ 184.00	
24	BONNET HINGE - LH / RH ? bt /	2	\$ 150.00	144.00
25	BONNET SIDE SEAL COVER - LH Xcm /	1	\$ 53.00	52.90
26	BONNET STOP BUFFER nn /	1	\$ 8.00	/
27	BONNET GAS FILLED STRUT Xsvl	1	\$ 123.00	
28	BONNET EDGE PROTECTION nn /	1	\$ 35.00	34.80
29	BONNET CATCH HOOK Xbt /	1	\$ 116.00	/
30	BONNET STRIKER - LH / RH Xnn	2	\$ 274.00	137.00
31	BONNET CATCH HOOK Xsvl Xnn	1	\$ 79.00	
32	BONNET LOCK WITH MICRO-SWITCH - LH / RH	2	\$ 491.00	245.50
33	BONNET RELEASE CABLE COVER Xsvl	1	\$ 12.00	
34	BONNET BOWDEN CABLE - CENTER Xsvl	1	\$ 71.00	
35	BONNET ENGINE SOUND ABSORBER Xsvl	1	\$ 275.00	
36	FRONT PLENUM CHAMBER COVER Xsvl	1	\$ 296.00	
37	NOTICE FOR VEHICLES WITH AUXILIARY HEATER Xsvl	1	\$ 9.00	
38	FRONT FENDER - LH bsvl /	1	\$ 1,016.00	/
39	FRONT FENDER ATTACHMENT PARTS Xnn	1	\$ 85.00	
40	FRONT FENDER BRACKET - LH REAR bt /	1	\$ 45.00	44.10
SUB TOTAL SPARE PARTS			\$ 6,826.00	5232.40

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMJ 3012 P
DAMAGED PARTS & PRICES

S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
41	FRONT FENDER BRACKET - LH CENTER <i>bt</i>	1	\$ 74.00	<i>73.30</i>
42	FRONT FENDER RIVET <i>na</i>	8	\$ 34.00	<i>73.60</i>
43	FRONT FENDER INSULATION - LH <i>? x su</i>	1	\$ 54.00	
44	FRONT FENDER CLOSING ELEMENT - LH <i>cm</i>	1	\$ 42.00	<i>41.10</i>
45	FRONT FENDER SEAL - LH <i>? x su</i>	1	\$ 43.00	
46	FRONT FENDER BRACE <i>bt</i>	1	\$ 122.00	<i>121.50</i>
47	FRONT FENDER CLOSING ELEMENT - LH <i>? cm</i>	1	\$ 76.00	
48	FRONT WHEEL HOUSING LINER - LH <i>de</i>	1	\$ 204.00	<i>203.50</i>
49	FRONT WHEEL HOUSING LINER ATTACHMENT PARTS <i>x su</i>	1	\$ 67.00	
50	A-PILLAR CONNECTING PLATE - LH INNER <i>x su</i>	1	\$ 261.00	
51	LOCK CARRIER CLOSING ELEMENT - LH FRONT <i>? x su</i>	1	\$ 106.00	
52	LOCK CARRIER <i>cm</i>	1	\$ 908.00	<i>907.50</i>
53	RADIATOR AIR GUIDE - LH <i>cm</i>	1	\$ 59.00	<i>58.60</i>
54	RADIATOR AIR GUIDE - RH <i>x su</i>	1	\$ 86.00	
55	RADIATOR AIR GUIDE SEAL - RH OUTER <i>x su</i>	1	\$ 10.00	
56	RADIATOR AIR GUIDE - UPPER CENTRE <i>x su</i>	1	\$ 21.00	
57	A/C CONDENSER WITH FLUID RESERVOIR <i>x su</i>	1	\$ 846.00	
58	A/C CONDENSER SEAL RING <i>x su</i>	1	\$ 16.00	
59	A/C CONDENSER SEAL RING <i>x su</i>	1	\$ 15.00	
60	ADDITIONAL RADIATOR <i>x su</i>	1	\$ 987.00	
SUB TOTAL SPARE PARTS		:	\$ 4,031.00	<i>1515.10</i>

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMJ 3012 P

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
61	RADIATOR BRACKET - LH / RH UPPER Xsu	2	\$ 94.00	
62	RADIATOR BUSH - LH / RH LOWER X su	2	\$ 24.00	
63	RADIATOR X su	1	\$ 1,177.00	
64	READY-MIX COOLANT X su	6	\$ 332.00	331.80
65	RADIATOR FAN WITH FAN RING Xsu	1	\$ 1,681.00	
66	WASH WATER RESERVOIR de	1	\$ 238.00	237.50
67	FRONT WINDSCREEN WASHER SYSTEM PUMP Xsu	1	\$ 147.00	
68	FRONT WINDSCREEN WASHER SYSTEM PUMP SEAL Xsu	1	\$ 4.00	
69	FRONT WINDSCREEN WASHER SYSTEM PUMP ELBOW FITTING Xsu	1	\$ 16.00	
70	HORN HIGH TONE - LH cm	1	\$ 239.00	238.50
71	FRONT WINDOW SLOT SEAL CHROME TRIM STRIP - LH Xsu		\$ 335.00	
72	FRONT LOWER CONTROL ARM - LH Xsu	1	\$ 422.00	
73	FRONT STABILIZER Xsu	1	\$ 479.00	
74	FRONT WHEEL BEARING HOUSING Xsu	1	\$ 669.00	
75	FRONT WHEELHUB WITH BEARING Xsu	1	\$ 554.00	
76	FRONT GUIDE JOINT Xsu	1	\$ 145.00	
77	FRONT COUPLING ROD Xsu	1	\$ 112.00	
78	FRONT DRIVE SHAFT WITH CONSTANT VELOCITY JOINTS - LH Xsu	1	\$ 1,615.00	
79	FRONT GAS SHOCK ABSORBER Xsu	1	\$ 301.00	
80	FRONT STEERING GEAR Xsu	1	\$ 6,113.00	
SUB TOTAL SPARE PARTS		:	\$ 14,697.00	807180

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMJ 3012 P

DAMAGED PARTS & PRICES

S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
81	FRONT STEERING BOX REPAIR SET ? <i>Xm</i>	1	\$ 28.00	
82	FRONT STEERING GEAR GREASE ? <i>Xm</i>	1	\$ 54.00	
83	FRONT TRACK ROD ? <i>Xm</i>	1	\$ 110.00	
84	FRONT TIE ROD END - LH ? <i>Xm</i>	1	\$ 138.00	
85	FRONT ASSEMBLY CARRIER ? <i>Xm</i>	1	\$ 1,309.00	
86	1 SET BONDED RUBBER BUSHES ? <i>Xm</i>	1	\$ 127.00	
87	FRONT NUMBER PLATE <i>Xm</i>	S/N	\$ 60.00	
88	METAL FILTER POWDER <i>Xm</i>	S/N	\$ 280.00	
89	ACRYLIC SEALANT <i>Xm</i>	S/N	\$ 180.00	
90	STONE CHIP <i>Xm</i>	S/N	\$ 180.00	
91	CAVITY WAX <i>Xm</i>	S/N	\$ 140.00	
92	SUNDRIES ? <i>new</i>		\$ 800.00	<i>39.10</i>
TOTAL SPARE PARTS		:	\$ 45,634.00	
TOTAL LABOUR CHARGES		:	\$ 24,590.00	
GRAND TOTAL		:	\$ 70,224.00	<i>39.10</i>

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME

: Rasul - Hp 90010068

SURVEYED DATE

: 13/06/24

AUTHORISED DATE

: 11 days

EXCESS COST

:

LIABILITY

:

REMARKS

:

Resurvey & part

PLEASE NOTE

:

THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY.
FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,

PREMIUM AUTOMOBILES PTE LTD

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT