

LEE BROTHERS AUTOMOTIVE PTE LTD

NO 1 KAKI BUKIT AVE 6 #02-47

AUTOBAY SINGAPORE 417883

Tel : 6509 5521 / 65095524 Fax : 6509 5523

Not Authorized
mercus
25/7/24
4/s & 6600
the photo after repair
5 days

The Motor Claims Dept.

AUTO & GENERAL INSURANCE (SINGAPORE) PTE LTD

190 CLEMENCEAU AVE

#03-01 SINGAPORE SHOPPING CENTRE

SINGAPORE 239924

SJX586G

ESTIMATE

VEHICLE NO : SNB1660L

MAKE/MODEL : HYUNDAI AVANTI

ACC DATE : 24.07.2024

PARTICULAR	UNIT PRICE	AMOUNT
QTY	SS	SS
<u>LIST PRICE</u>		
1 1 REAR BOOT LID	2,023.20	2,023.20
2 1 REAR BOOT OUTER GARNISH	561.90	561.90
3 1 REAR BOOT CAMERA	837.90	837.90 X
4 1 REAR BOOT LOGO	58.90	58.90
5 1 REAR BOOT EMBLEM 'AVANTE'	60 112.60	112.60
6 1 REAR BOOT EMBLEM 'S'	40 68.90	68.90
7 1 REAR BOOT REFLECTOR -CTR	1,025.80	1,025.80
8 1 REAR BOOT INNER LOCK	180 285.60	285.60
9 1 REAR BOOT INNER TRIM	261.90	261.90 X
10 1 REAR BOOT LOCK STRIKER	48.20	48.20 X
11 2 REAR BOOT HINGES -R/L	185.00	370.00 X
12 2 REAR BOOT STOPPER	18.60	37.20 X
13 1 REAR BOOT W/STRIP	190.60	190.60
14 1 REAR BUMPER	490.40 671.60	671.60
15 1 REAR BUMPER DISFUSSE	471.00	471.00
16 4 REAR BUMPER PDC SENSOR	241.50	966.00 X
17 2 REAR BUMPER REFLECTOR -R/L	89.90	179.80 X
18 1 REAR BUMPER REINFORCEMENT	294.80 485.60	485.60
19 2 REAR BUMPER TOP BRACKETS	55.60	111.20
20 2 REAR BUMPER LOWER BRACKETS	55.60	111.20 X
21 2 REAR BUMPER SIDE RETAINERS -R/L	89.50	179.00 X
22 1 REAR END PANEL	535.00	535.00
23 1 REAR END PANEL GARNISH	126.60	126.60
24 1 REAR FLOOR BOARD	489.60	489.60
25 2 REAR FENDER INNER TRIMS -R/L	481.60	963.20 X
26 2 REAR LICENCE LAMPS	58.60	117.20 X
27 2 REAR TAILLAMPS - RH/LH	596.90	1,193.80
28 2 REAR TAILLAMP PANELS -R/L	235.00	470.00 X
29 1 REAR SMART KEYLESS SENSOR	182.60	182.60 X
		13,136.10
	Less 20%	2,627.22
		10,508.88

590.40 x 2 = 1180.80

LEE BROTHERS AUTOMOTIVE PTE. LTD.

PARTICULAR		UNIT PRICE	AMOUNT
QTY		S\$	S\$
<u>SPECIAL NETT ITEMS</u>			
1	1 (SET) REAR BOOT INNER TRIM CLIP	50.00	50.00 X
2	1 (SET) REAR BUMPER CLIP	60.00	60.00 30
3	1 (SET) REAR NUMBER PLATE	65.00	65.00 40
			175.00
<u>LABOUR CHARGES :</u>			
1	TO CHECK REAR ELECTRICAL WIRING		50.00 20
2	TO REMOVE & REFIX REAR INTERIOR TRIMS TO ASSIST REPAIR		120.00 60
3	TO TUFF KOTE		100.00 60
4	TO PUTTY, SPRAY PAINT & POLISH AFFECTED PARTS		1,200.00 1000
5	TO PANEL BEAT, CUT, WELD, REMOVE & REPLACE DAMAGED PARTS		1,200.00 800
			2,670.00

ESTIMATE PARTS AND LABOUR GRAND TOTAL : \$ 13,353.88

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

p-7840.60
202
6272.48
70
1940
8242.48
202
6624