

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315 Reg. No: 199607198R GST Reg. No. 19-9607198-R

| Affiliated to Federation Internationale Des Experts En Automobile | | | | | |
|--|---|--|-----------------|-----------------------|--|
| MS | ALLIED WORLD AS | SSURANCE COMPANY LTD | Ref: | CS/AWA24070401/Enp3e2 | |
| | (SINGAPORE BRA | | Date: | 02/08/2024 | |
| | | #08-01 (8TH FLOOR) ON SINGAPORE 079914 | Code: | AWA | |
| 1. | Policy Particulars :- THIRD PARTY CLAIM | | | | |
| | Insured Veh. | GBD 8004S | Veh. Inspected | SHD 7121Y | |
| | Policy No. | CSG24VFCPA00010 | Coverage | 0 | |
| | Claim No. | CSG24VFCPA00010/HLF | Excess | \$0.00 | |
| | Assign From | - | Assign Date | 25/07/2024 | |
| 2. | 2. Vehicle Details | | | | |
| | Make & Model | HYUNDAI 140 | C.C | 1685 | |
| | Engine No. | D4FDGU673789 | Year of Reg. | 10/11/2016 | |
| | Chassis No. | KMHLB41UMHU096251 | Colour | BLUE | |
| | Odometer | 798335 KM | Steering | IN ORDER | |
| | Brakes | IN ORDER | General | GOOD | |
| | Modification(s) | RIMS: SPORTS RIM | | | |
| 3. | 3. Conditions of Tyres | | | | |
| | | Size | Make | Balance (mm) | |
| | R/H Front Tyre | 205/60 R16 | GITI | 6 | |
| | L/H Front Tyre | 205/60 R16 | GITI | 6 | |
| | R/H Rear Tyre | 205/60 R16 | GITI | 6 | |
| | L/H Rear Tyre | 205/60 R16 | GITI | 6 | |
| 4. Description of Damages | | | | | |
| THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY. | | | | | |
| DAMAGES SEE DETAILS. | | | | | |
| 5. | | General Information | | | |
| | Accident Date | 24/07/2024 | Inspection Date | 25/07/2024 | |
| | Survey held at | COMFORTDELGRO ENGINEERING PTE LTD 59 LOYANG DRIVE SINGAPORE 508969 | | | |
| 5a. | Remarks | | | | |
| A) THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. | | | | | |
| 5b. Estimate Days of Repair | | | | | |
| | | | | | |

ESTIMATED NORMAL PERIOD FOR REPAIR: 3 Working Days