



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,  
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No.  
19-9607198-R

## Affiliated to Federation Internationale Des Experts En Automobile

MS ALLIED WORLD ASSURANCE COMPANY LTD (SINGAPORE BRANCH) 60 ANSON ROAD #08-01 (8TH FLOOR) MAPLETREE ANSON SINGAPORE 079914	Ref: CS/AWA24070401/Enp3e2 Date: 07/08/2024 Code: AWA
---	---

### 1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	GBD 8004S	Veh. Inspected	SHD 7121Y
Policy No.	CSG24VF CPA00010	Coverage	0
Claim No.	CSG24VF CPA00010/HLF	Excess	\$0.00
Assign From	-	Assign Date	25/07/2024

### 2. Vehicle Details

Make & Model	HYUNDAI I40	C.C	1685
Engine No.	D4FDGU673789	Year of Reg.	10/11/2016
Chassis No.	KMHLB41UMHU096251	Colour	BLUE
Odometer	798335 KM	Steering	IN ORDER
Brakes	IN ORDER	General	GOOD
Modification(s)	RIMS: SPORTS RIM		

### 3. Conditions of Tyres

	Size	Make	Balance (mm)
R/H Front Tyre	205/60 R16	GITI	6
L/H Front Tyre	205/60 R16	GITI	6
R/H Rear Tyre	205/60 R16	GITI	6
L/H Rear Tyre	205/60 R16	GITI	6

### 4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY.

DAMAGES SEE DETAILS.

### 5. General Information

Accident Date	24/07/2024	Inspection Date	25/07/2024
Survey held at	COMFORTDELGRO ENGINEERING PTE LTD 59 LOYANG DRIVE SINGAPORE 508969		

### 5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.  
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

### 5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: 3 Working Days