

SG Zoom Garage Pte Ltd**53 Ubi Avenue 1, #01-43 Paya Ubi Industrial Park Singapore 408934****UEN number: 202308291E**

Trust Motor Leasing Pte Ltd

Third Party Insurer: III
Date of accident: 25 July 2024

Date: 26 July 2024

Estimate To Repair

SMZ1934H - HONDA MOBILIO

Chassis No : MRHDD4870FP000169

S/No	Quantity	Description	Amount
		LIST ITEMS	
1	1 pc	bonnet X	\$ -
2	2 pc	bonnet hinge - LH / RH X	\$ -
3	1 pc	headlamp - LH / CUT	\$ -
4	1 pc	headlamp bracket - LH ?	\$ -
5	1 pc	front grille assy ?	\$ -
6	1 pc	front grille garnish / CUT	\$ -
7	1 pc	front grille 'Honda' emblem badge ?	\$ -
8	1 pc	radiator assy X	\$ -
9	1 pc	air-con condenser X	\$ -
10	1 pc	support panel X	\$ -
11	1 pc	front bumper / OR	\$ -
12	1 pc	front bumper reinforcement ?	\$ -
13	1 pc	front bumper sponge ?	\$ -
14	2 pc	front bumper side retainer - LH / RH / OR	\$ -
15	1 pc	front bumper towing cover - MJ	\$ -
16	1 pc	front bumper lower grille ?	\$ -
17	1 pc	front bumper fog lamp - LH / CUT	\$ -
18	1 pc	front bumper fog lamp cover - LH / CUT	\$ -
19	1 pc	front bumper fog lamp cover chrome - LH / CUT	\$ -
20	2 pc	front bumper clip @ \$ - / OR	\$ -
21	1 pc	front fender - LH X R	\$ -
22	1 pc	front fender inner shield - LH ?	\$ -
23	12 pc	front fender inner shield clips - LH @ \$ - ?	\$ -
		Less 20%	\$ -
			\$ -
		SPECIAL NETT ITEMS	
24	1 pc	front number plate / CUT	\$ 40.00
			\$ 40.00
		balance c/f	\$ 40.00

SG Zoom Garage Pte Ltd

53 Ubi Avenue 1, #01-43 Paya Ubi Industrial Park Singapore 408934

UEN number: 202308291E

Trust Motor Leasing Pte Ltd

Third Party Insurer: III

Date of accident: 25 July 2024

Date: 26 July 2024

Estimate To Repair

SMZ1934H - HONDA MOBILIO

Chassis No : MRHDD4870FP000169

S/No	Quantity	Description	Amount
		Balance b/f	\$ 40.00
		LABOUR & MISC. CHARGES	
1		To remove & refit air-con condenser, radiator and refill air-con gas.	\$ 150.00 X
2		To check electrical lighting concerned.	\$ 100.00 30
3		To panel beat & straighten front chassis frame, to cut & weld support panel, including replacement of parts & align where necessary, to refit & adjust the same.	\$ 1,200.00 300
4		Putty and spray painting of the affected portion.	\$ 1,200.00 400
5		To rust-proofing of the affected areas.	\$ 80.00 30
			\$ 2,730.00
		Grand Total	\$ 2,770.00

Steve (LKK)

26/7/24, 2.00pm

m R

L/S

Ly AL Ry

4 dys

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature: _____

Date: _____