LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315 Reg. No: 199607198R GST Reg. No. 19-9607198-R

To: INDIA INTERNATIONAL INSURANCE PL From: LKK Auto Consultants Pte Ltd

64 CECIL STREET

#05-02 IOB BUILDING SINGAPORE 049711

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park Singapore 408933

Attn: LOGANATHAN S/O AGORAM Date: 13/08/2024

PRELIMINARY ADVICE

Vehicle NoSMZ 1934HAccident Date25/07/2024MakeHONDA MOBILO SVCLAIM No.TBAAssignment Date25/07/2024Excess-Inspection Date26/7/2024Est. Duration of Repair4

Inspected At: SG ZOOM GARAGE PTE LTD

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Workshop Estimate Amount:	\$ 9,562.00
Revised Estimate Amount:	\$ 3,311.20
"Check" Items Amount	\$0.00
Total	\$ 3,311.20

Total Loss Consideration

Book Value	\$0.00
Market Value	\$0.00

COE / PARF Rebate

Salvage Value \$0.00

Margin for Repair

Remarks

[]	The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage.
		Kindly let us have your authorisation.

[] The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.

[]	Other comments: Please note that the preliminary advice amount (Revised & Check Items) stated are subject to
		consistency check, part prices and labour cost.