TONG LUCK AUTO PTE LTD

160 SIN MING DRIVE #07-01/06 SIN MING AUTOCITY, SINGAPORE 575722 Tel: 6250 0088 Fax: 6250 5545 Email: operation@tlauto.com.sg

GST No: 201700521W UEN No: 201700521W

MSIG INSURANCE (SINGAPORE) PTE LTD 4 SHENTON WAY #21-01 SGX CENTRE SINGAPROE 068807

24 July 2024

Attn: MOTOR CLAIMS DEPT

Dear Sirs / Madam,

RE: ACCIDENT INVOLVING VEHICLE NO.: SMW5773U & GBM1331X ON 13/07/2024 @, 14:05 HRS ALONG JLN TOA PAYOH TOWARDS KIM KEAT AVE

We hereby authorized by our client MERCEDES-BENZ FLEET MANAGEMENT SINGAPORE PTE LTD, the owner/driver of the above mentioned vehicle No.: SMW5773U

We notice that the above accident was caused by your insured/driver negligent driving and/or management of motor vehicle No.: GBM1331X

Therefore we are instructed by our client to claim against you/your insured driver in connection with the above captioned accident involving our client's vehicle No.: SMW5773U and vehicle No.: GBM1331X by your insured/driver at the material time. As a result, our client's vehicle was damaged and our client has been put to loss and expenses. Please assign your surveyor to inspect the above mentioned vehicle in the next 48hrs. Filling which, we will proceed to the repair of the vehicle. Details of claim will submitted to you in due course.

The vehicle is now garage at:

TONG LUCK AUTO PTE LTD

160 Sin Ming Drive

#07-01/06 Sin Ming Autocity

Singapore 575722 Tel: 6250 0088

Your kind attention to the matter would be much appreciated.

TONG LUCK AUTO PTE LTD



TONG LUCK AUTO PTE LTD

160 SIN MING DRIVE #07-01/06 SIN MING AUTOCITY, SINGAPORE 575722

Tel: 6250 0088 Fax: 6250 5545 Email: operation@tlauto.com.sg GST No: 201700521W UEN No: 201700521W

PAGE: 1

: MERCEDES-BENZ FLEET MANAGEMENT SINGAPORE P1 M/S

1 GATEWAY DRIVE #15-08

WESTGATE TOWER SINGAPORE 608531

TEL:

FAX:

ATTN: ACCOUNTS DEPT

YOUR REF NO **CLAIM TYPE**

: GBM1331X : THIRD PARTY

TP INS. CO. : MSIG INSURANCE (SINGAPORE) PTE LTD

ACCIDENT DATE : 13/07/2024 TP VEH REG NO : GBM1331X

ESTIMATE

NO

: QUOT202407-000057(00)

DATE

: 24/07/2024

POLICY NO

: SP2003907937

VEH REG NO : SMW5773U

MAKE/MODEL: MERCEDES BENZ GLA200

SUV PROGRESSIVE

CHASSIS NO : W1N2477872J134779

ENGINE NO

: 28291480389869

REG. DATE : 2020

Estimate Repair Cost to Vehicle No: SMW5773U

	Description	Quantity	Unit Price	Amount
			<u>S\$</u>	<u>S\$</u>
	NET PRICE			
1	Rear door - LH	1	2,565.00	2,565.00
2	Rear door trimboard rivet - LH	20	12.00	240.00
3	Rear door weatherstrip - LH	1	386.00	386.00
4	Rear door protector - LH	1	256.00	256.00
5	Rear door arch garnish - LH	1	256.00	256.00
			_	3,703.00
			Less 10%	370.30
			_	3,332.70
	LABOUR			
6	To remove & refit LH rear damaged door interior mechanism & glass to new door	1	150.00	150.00
7	To check and rectify wiring system	1	80.00	80.00
8	To panel beat & straighten LH rear door hinges, LH rear fender, including replacement of parts & align where necessary, to refit and adjust the same	1	800.00	800.00
9	To putty & spray paint on affected areas	1	800.00	800.00
10	To apply rust-proofing on replaced and repaired panels	1	80.00	80.00
			_	1,910.00
			TOTAL	S\$ 5,242.70
		ADD GST @ 9.00%		471.84
		G	GRAND TOTAL	

SINGAPORE DOLLAR FIVE THOUSAND SEVEN HUNDRED FOURTEEN AND CENTS FIFTY-FOUR ONLY

FOR TONG LUCK AUTO PTE LTD

AUTHORISED SIGNATURE

SJ0G247F000P / JP Knights Pte Ltd ENTRY DATE & TIME: 15/07/2024 11:25 (SGT) SUBMITTED BY: Flash Reporting VERSION: 1 (15/07/2024 11:25 (SGT))

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

- Please report <u>correctly</u> the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Actual Driver
 3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate policy liability.

- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.

 5. Any false reporting may be referred to the Police for investigation.

 6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.

 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of First Submission 15/07/2024 11:25 (SGT) Reported by **Actual Driver** Date of Accident 13/07/2024 14:05 (SGT) Exact Location of Accident Jln Toa Payoh, Singapore Additional Location Information TOWARDS KIM KEAT AVE Country/State of Loss Singapore

DETAILS OF OWN VEHICLE Vehicle Registration Number SMW5773U INSURED/POLICYHOLDER Is company? Yes Name Of Registered Owner MERCEDES-BENZ FLEET MANAGEMENT SINGAPORE PTE I TD Company Reg No 1XXXXX7787 Email Address too_tong.tan@mercedes-benz.com Mobile Phone No (Phone) +65-98281256 Alternative Phone No (Office) +65-82821711 VEHICLE PARTICULARS Manufacturer Mercedes Model ,.... **GLA200 SUV PROGRESSIVE** Variant Exact purpose for which vehicle was being used at time of accident Private use Are you claiming under your own insurance policy for repair to No - Claiming third party your vehicle? Vehicle Category Private car Transmission Auto CC 1332 INSURANCE COMPANY Name of Insurance Company Allianz Insurance Singapore Pte. Ltd. Policy Number / Cover Note Number SP2003907937 DRIVER Name of Driver TANG CHIH HUA SXXXX344G

02/06/1992

Date Of Birth

Vehicle Category	Commercial vehicle			
Name of Driver	ARUM			
Contact Number	(Phone) +65-85757506			
Address	<u>-</u>			
Address complement	-			
Postcode	-			
Insurance Company Name	-			
Nature Of Damage	-			
Details of property damaged in accident				
No. Of Passenger (Including Driver)				

Describe Circumstances of the Accident

ON 13/07/24 AT ABOUT 14:05 HRS WHILE I WAS DRIVING WITH VEHICLE A BEARING REGISTRATION NUMBER SMW5773U ALONG LOR 7 TOA PAYOH TOWARDS KIM KEAT AVE FOR PERSONAL PURPOSE. WHILE TRAVELLING ALONG LOR 7 TOA PAYOH WITHOUT STOPPING AT THE SLIP RD STOP SIGN VEHICLE B BEARING REGISTRATION NUMBER GBM1331X GRAZED ON LEFT REAR BODY PANEL OF VEHICLE A. NOBODY INJURED OR CONVEYED TO HOSPITAL.

Declaration

IWe declare the foregoing particulars are true in every respect

Policyholder's Signature / Date &

Driver's Signature (If driver is not the policyholder) / Date 8. Time

100EH

Witnessed by Reporting Centre Personnel

13/06/24 - 15:50 HRS