

FALCON AIR AUTO SERVICES PTE LTD

Tel No. :

CHINA TAIPING INSURANCE (S) PTE LTD
3 ANSON ROAD
#16-00 SPRINGLEAF TOWER S(079909)

Attention : Motor Claim Department

Contact : 63896111 Fax No. : 62221033

Estimate : ES709553

Date : 22/07/2024

Vehicle Num. : GBF 9086M

Make/Model : TOYOTA LITEACE

Chassis/Eng# :

Accident Date : 18/07/2024

Claim No. :

Reference :

Policy No. :

not Authorized
mercus
23/7/24
1/5 \$ 5500
Tel. 63896111
H. 62221033

S/N	Quantity	Particular	Unit Price	Amount S\$
-----	----------	------------	------------	------------

LIST ITEMS :				
1.	1PC	REAR BUMPER		784.96 ✓
2.	2PCS	REAR BUMPER SIDE RETAINER	109.34	218.68 X
3.	1PC	N/S REAR CORNER PANEL		162.84 X
4.	2PCS	TAILLAMP	598.27	1,196.54 1/2 C
5.	1PC	TAILGATE	3269.60	3,804.98
6.	1PC	TAILGATE LOGO		118.36 ✓
7.	1PC	TAILGATE GL STICKER	86.50	97.22 ✓
8.	1PC	TAILGATE LITEACE STICKER	60.00	98.13 ✓
9.	1PC	TAILGATE OUTER GARNISH		381.93 X
10.	1PC	REAR NUMBER PLATE LAMP		131.26 X
11.	1PC	TAILGATE LOCK		427.84 X
12.	1PC	TAILGATE WEATHERSTRIP		394.26 ✓
13.	1PC	TAILGATE INNER TRIM BOARD	399.10	511.34 ✓
14.	1PC	REAR END PANEL - OUTER		589.18 ✓
15.	1PC	REAR END PANEL INNER		784.73 X
16.	1PC	REAR END PANEL GARNISH		699.28 X
List Total S\$:				10,401.53
25.00% Discount S\$:				2,600.38
				7,801.15
SPECIAL NETT ITEMS :				
1.	1SET	REAR BUMPER CLIP	30	50.00

CONTINUE / ...

FALCON AIR AUTO SERVICES PTE LTD

Tel No. :

CHINA TAIPING INSURANCE (S) PTE LTD
3 ANSON ROAD
#16-00 SPRINGLEAF TOWER S(079909)

Attention : Motor Claim Department

Contact : 63896111 Fax No. : 62221033

Estimate : ES709553

Date : 22/07/2024

Vehicle Num. : GBF 9086M

Make/Model : TOYOTA LITEACE

Chassis/Eng# :

Accident Date : 18/07/2024

Claim No. :

Reference :

Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
2.	1SET	REVERSE SENSOR <i>110</i>	<i>200</i>	250.00 <i>200</i>
3.	1PC	TAILGATE WEIGHT STICKER <i>11</i>		100.00 <i>X</i>
4.	1PC	70KM/H STICKER <i>11</i>		25.00 <i>10</i>
5.	1PC	5 PAX STICKER <i>11</i>		25.00 <i>10</i>
6.	1PC	REAR NUMBER PLATE <i>one</i>		50.00 <i>40</i>
7.	1SET	TAILGATE INNER TRIM BOARD CLIPS <i>11</i>		50.00 <i>30</i>
8.	1PC	REAR FLOOR CARPET <i>one</i>		500.00 <i>200</i>
9.	1SET	REVERSE CAMERA <i>500</i>		500.00 <i>X</i>
10.	1PC	TAILGATE SEALANT <i>11</i>		80.00 <i>40</i>
11.	1PC	TAILGATE GLASS SEALANT <i>11</i>		50.00 <i>X</i>
12.	1PC	TAILGATE GLASS INNER SEAL <i>11</i>		50.00 <i>20</i>
Special Nett Total S\$:				1,730.00
LABOUR :				
TO CHECK LIGHT AND WIRING				50.00 <i>20</i>
TRANSFER TAILGATE GLASS				120.00 <i>120</i>
TRANSFER TAILGATE PARTS				100.00 <i>60</i>
INSTALL REVERSE SENSOR				80.00 <i>30</i>
INSTALL REVERSE CAMERA				<i>11</i> 120.00 <i>X</i>
ANTI-RUST				120.00 <i>50</i>
TO APPLY BODY SEALANT ON BODY JOINTS				120.00 <i>40</i>
LABOUR/PANEL BEATING				1,000.00 <i>600</i>

CONTINUE / ...

FALCON AIR AUTO SERVICES PTE LTD

Tel No. :

CHINA TAIPING INSURANCE (S) PTE LTD
3 ANSON ROAD
#16-00 SPRINGLEAF TOWER S(079909)

Attention : Motor Claim Department

Contact : 63896111 Fax No. : 62221033

Estimate : ES709553

Date : 22/07/2024

Vehicle Num. : GBF 9086M

Make/Model : TOYOTA LITEACE

Chassis/Eng# :

Accident Date : 18/07/2024

Claim No. :

Reference :

Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
		SPRAY PAINTING		1,000.00 <i>800</i>
		Labour Total S\$:		2,710.00

E. & O.E.

Total S\$: 12,241.15

=====

for FALCON AIR AUTO SERVICES PTE LTD

TAMPINES BRANCH

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

*P 6106-83**252**P- 4560-12**S.W- 580**L- 1720**6880-12**202**5204*