



Pte Ltd

TeamWork Garage Pte Ltd

53 Ubi Avenue 1 #01-23/24 Spore 408934

Paya Ubi Industrial Park


Tel : 6844 2475

E-mail : claims@teamworkgarage.com

Register number : 201015366H

REPAIR PERFORMA INVOICE

bizSAFE
S T A R



Vehicle number	SJK5471P
Make / Model	HONDA STREAM
Chassis number	RN61053639
Accident date	24/7/24
Reference	2407-20

Qty	Particulars	Unit Price - SGD \$
<u>PARTS REPLACEMENT - LIST ITEMS</u>		
1	FRONT BUMPER <i>do/cu</i>	1185.00 ✓
1	FRONT BUMPER RETAINER LH <i>11</i>	47.50 <i>x</i>
1	FRONT BUMPER REINFORCEMENT <i>1</i>	340.60 <i>x</i>
1	FRONT BUMPER LOWER GRILLE <i>cu</i>	204.65 ✓
1	FRONT HEADLAMP LH <i>cu</i>	1218.58 ✓
1	FRONT HEADLAMP BRACKET LH <i>cu</i>	60.30 ✓
1	FRONT GRILLE <i>cu</i>	387.50 ✓
		3444.13
	Less 20%	688.83
	Subtotal	2755.30
	Balance C/F	2755.30
<u>PARTS REPLACEMENT - SPECIAL NETT ITEMS</u>		
1 SET	FRONT BUMPER CLIP <i>711</i>	50.00 <i>40</i>
1 SET	FRONT GRILLE CLIP <i>11</i>	50.00 <i>x</i>
	Subtotal	100.00
	Balance C/F	2855.30
<u>LABOUR AND MISCELLANEOUS CHARGES</u>		
1	CHECK WIRING AND LIGHTINGS SYSTEM	120.00 <i>20</i>
2	REMOVE AND REFIT FRONT TRIMS AND GARNISHES	1715.00 <i>x</i>
3	PANEL BEATING ON AFFECTED AREAS	600.00 <i>300</i>
4	SPRAY PAINTING ON AFFECTED AREAS	600.00 <i>300</i>
5	APPLY ANTI RUST ON AFFECTED AREAS	1150.00 <i>x</i>
	Subtotal	1620.00
	Grand total	4475.30

not added
1/5 #2100
chupka mny
means
90096608
31/7/24

LIKKA Auto Consultants hereby notify the Repainer of the following:

- To measure before/after spray painting
- To display damaged parts for assessment
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Expenditure item(s) must be reasonable and is subject to final approval from Insurance Company

Acknowledged by Repainer

Signature:

Date: