

T & B MOTOR REPAIRS SERVICES PTE LTD

160 SIN MING DRIVE #08-03 SIN MING AUTOCITY SINGAPORE 575722

DBS CURRENT A/C : 018-015151-0

Tel No. : 6454 8007

E-Mail : tbmotor@hotmail.sg

Tax Reg. No. : 199001597D Buss. Reg. No. : 199001597D

WITHOUT PREJUDICE

KELVIN GWEE
9 YISHUN STREET 51
#08-20 SINGAPORE 767970

Attention : Motor Claim Department

Not Authorised
Plumby After Party
11 Lyr @ 9500/-
6 days

Estimate : ES003557

Date : 17/07/2024

Vehicle Num. : SNF5600M

Make/Model : PORSCHE PANARAMA

Chassis/Eng# :

Accident Date : 17/07/2024

Claim No. :

Reference :

Policy No. : 11450152

S/N	Quantity	Particular	Unit Price	Amount S\$
-----	----------	------------	------------	------------

1.	1	LIST ITEMS :		
2.	1	REAR BUMPER	4120	CM 4,800.00 ✓
3.	1	REAR BUMPER RETAINER		B 245.00 X
4.	1	REAR BUMPER REFORCEMENT		B 1,995.00 ✓
5.	1	REAR END PANEL	2216	B 2,680.70 ✓
6.	2	PARKING SENSOR		280.00 1,120.00 ✓
7.	2	REAR LEFT EXHAUST		3,680.00 7,360.00 ✓
8.	2	REAR LEFT EXHAUST TIP	0640	1,150.00 2,300.00 ✓
		REAR BUMPER PAT		685.00 1,370.00 ✓
				21,870.70
				2,187.07
				19,683.63

List Total S\$:

10.00% Discount S\$:

LABOUR :

- 1) TO REMOVE BUMPER, REAR PANEL PULL AND KNOCKING
- 2) TO SPRAY REAR BUMPER AND LOWER SKIRT
- 3) COMPUTER DIAGNOSE & RESET SENSOR PARKING FAULT

Labour Total S\$:

12000
2,600.00
1,400.00 9000
nn 350.00 ✓
4,350.00

SingDollars : Twenty-Four Thousand Thirty-Three & Cents Sixty-Three Only

E. & O.E.

Total S\$: 24,033.63

for T & B MOTOR REPAIRS SERVICES PTE LTD

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

T & B MOTOR REPAIRS SERVICES PTE LTD

160 SIN MING DRIVE #08-03 SIN MING AUTOCITY SINGAPORE 575722

DBS CURRENT A/C : 018-015151-0

Tel No. : 6454 8007

E-Mail : tbmotor@hotmail.sg

Tax Reg. No. : 199001597D Buss. Reg. No. : 199001597D

WITHOUT PREJUDICE

KELVIN GWEE
9 YISHUN STREET 51
#08-20 SINGAPORE 767970

Supplementary Estimate : ES003558

Attention : Motor Claim Department

Date : 17/07/2024
Vehicle Num. : SNF5600M
Make/Model : PORSCHE PANARAMA
Chassis/Eng# :
Accident Date : 17/07/2024
Claim No. :
Reference :
Policy No. : 11450152

S/N	Quantity	Particular	Unit Price	Amount S\$
-----	----------	------------	------------	------------

LABOUR :

- 1) LABOUR TO REMOVE INSIDE GARNISH IN ORDER TO REPAIR REAR END PANEL
- 2) LABOUR TO REMOVE EXHAUST AND BELOW COVER AND BRACKET AND FIX
- 3) TO REPAIR REAR EXHAUST
- 4) TO SPARY REAR END PANEL ,ANTI RUST
- 5) EXHAUST HEAD SHIELD LEFT → 7108

Labour Total S\$:

580.00

450.00

600.00

180.00

368.90

2,178.90

SingDollars : Two Thousand One Hundred Seventy-Eight & Cents Ninety Only

E. & O.E.

Total S\$: 2,178.90

for T & B MOTOR REPAIRS SERVICES PTE LTD