

YEW HOK AUTO SERVICES

522 Bedok North Ave 1, #11-310, Singapore 460522

H/P: 8285 7623

Email: yhlee@outlook.sg

not full
air
mirror
28/17/24
2/5 & 5300
light. After -
5 days

Vehicle number: GBK2800M

Vehicle Made & Model: NISSAN NV 350

Qty	Nett Items		Amount \$
1	Tailgate	2011.60	2,596.60 ✓
1	Tailgate glass	11	891.10 X
1	Tailgate logo	11	86.60 ✓
1	Tailgate emblem "NV350"	11	110.20 ✓
1	Tailgate emblem "URVAN"	11	98.60 ✓
1	Tailgate chrome moulding	one	311.40 ✓
1	Tailgate inner lock	2 only	280.60 ✓
1	Tailgate inner lock actuator	11	291.30 X
1	Tailgate inner board	11	281.90 X
1	Tailgate lock striker	11	86.90 X
1	Tailgate w/strip	10.11	149.50 211.60 ✓
2	Tailgate dampers - L/R @ 195.70	11	391.40 X
2	Taillamps - L/R @ 411.50	11	823.00 X
1	Rear bumper	2011.60	686.30 ✓
2	Rear bumper side retainers - L/R @ 55	11	110.00 X
1	Rear end panel	401.50	461.90 ✓
1	Rear end panel inner member	501.50	560.50 ✓
1	Rear step panel	513.50	291.60 ✓
Sub-total			8,571.50
Less 10%			857.15
Total Nett			7,714.35

Vehicle number: GBK2800M

Vehicle Made & Model: NISSAN NV 350

Special Nett Items

1 set	Tailgate glass sealant	121	80.00	40
1 set	Tailgate glass foam tape	121	65.00	20
1 set	Rear bumper clip	121	60.00	30
1 set	Rear reverse sensor	molten	280.00	200
1	Rear sticker "70 KM/H"	121	10.00	✓
1	Rear sticker "8 PAX"	121	10.00	✓
1 set	Tailgate inner board clip	121	60.00	X
			565.00	

Labour charges

To respray undercoating	120.00	60
To remove, refix tailgate glass	180.00	100
Transfer & reinstall tailgate components to new tailgate	150.00	60
To remove, refix rear interior trims to assist repair	120.00	X
To check rear electrical wiring	50.00	20
To respray painting and etc	1,200.00	800
Panel beating, cut, weld remove & replacing above parts	1,200.00	800
Total Labour		
		3,020.00

ESTIMATE PARTS AND LABOUR GRAND TOTAL \$ 11,299.35

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) for the resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Page 2 of 2

125012
102
1110.80
310
1840
6660.8
22
5328.