



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933
TEL: 6256 3561 FAX: 6256 4315
Reg. No: 199607198R GST Reg. No.
19-9607198-R

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO SGS 6622H

REPLACEMENT OF PARTS				
Qty	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
1	REAR BUMPER	TORN	\$2,254.00	\$1,766.21
1	REAR BUMPER LOWER CHROME MOULDING	SCRATCHED	\$975.00	\$282.00
1	REAR BUMPER RETAINER LH	NOT NECESSARY	\$275.00	\$0.00
1	REAR BUMPER RETAINER RH	NOT NECESSARY	\$275.00	\$0.00
1	REAR BUMPER REFLECTOR LH	NOT NECESSARY	\$285.00	\$0.00
1	REAR BUMPER REFLECTOR RH	NOT NECESSARY	\$285.00	\$0.00
1	REAR BUMPER BRACKET LH	NOT NECESSARY	\$175.00	\$0.00
1	REAR BUMPER BRACKET RH	NOT NECESSARY	\$175.00	\$0.00
1	REAR BUMPER CENTER BRACKET	NOT NECESSARY	\$385.00	\$0.00
1	REAR BUMPER LOWER BRACKET	NOT NECESSARY	\$275.00	\$0.00
	LESS 5.00 / 10.00% DISCOUNT		(\$267.95)	(\$204.82)
			\$5,091.05	\$1,843.39
Special Nett				
Qty	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
1	SET REAR BUMPER CLIPS (SN)	NOT NECESSARY	\$80.00	\$0.00
1	SET JOINT SEALANT (SN)	NOT NECESSARY	\$100.00	\$0.00
			\$180.00	\$0.00
Labour				
	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
	CHECK WIRING AND LIGHTING SYSTEM		\$150.00	\$20.00
	REMOVE AND REFIT FRONT & FRONT MIRROR		\$300.00	\$0.00
	APPLY ANTI RUST ON AFFECTED AREAS		\$120.00	\$0.00
	PANEL BEATING ON AFFECTED AREAS AND RENEW DAMAGE		\$1,000.00	\$200.00
	SPRAY PAINTING ON AFFECTED AREAS		\$1,000.00	\$200.00
			\$2,570.00	\$420.00
GRAND TOTAL			\$7,841.05	\$2,263.39
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			\$1,800.00
Report Ref No: CS/FCI24070450/Unp3				



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315
Reg. No: 199607198R GST Reg. No.
19-9607198-R

CKS

MARCUS CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.