

Progressive Car Care Pte Ltd

Blk 3022A Ubi Road 1 #01-45/46 Singapore 408716

TEL: 6741 5336 FAX: 6741 7208

Email: claims@proccarcare.com.sg

GST REG NO: 201006949C Company Reg No: 201006949C

*Not Allowed
meras
21/8/24
3 days 2/58 1650
Theresa Heng*

INDIA INTERNATIONAL INSURANCE PTE LTD

64 Cecil Street
IOB Building #04-05
Singapore 049711

Tel: 63476100

Fax: 62244174, 62257743

Attn: Motor Claim Department

Your Ref No: TP 0724-8151

Claim Type: Third Party

Accident Date: 26 July 2024

TP Veh Reg No: PA1997Y

Estimate No: EST1511564
Date: 27 Jul 2024
Policy No: MT/01431558
Veh Reg No: SKW8666A
Make/Model: HONDA FIT 1.3GF CVT
Chassis No: GK31331080
Engine No: L13B1437285
Reg. Date: 12 Mar 2019

Estimate Repair Cost to Vehicle No: SKW8666A

Description	Unit Price	Quantity	List Price SGD	Amount SGD
List Price				
1 FRONT BUMPER	657.70	1 PC <i>100%</i>	657.70 ✓	
2 FRONT BUMPER SISDE RETAINER - LH/RH	15.40	2 PC <i>11</i>	30.80 X	
3 FRONT BUMPER CLIPS	3.90	10 PC <i>11</i>	39.00 X	
4 FRONT BUMPER REINFORCEMENT	258.00	1 PC <i>11</i>	258.00 X	
5 FRONT BUMPER CENTER LOWER GRILLE	180.70	1 PC <i>11</i>	180.70 X	
6 FRONT BUMPER TOW COVER	18.70	1 PC <i>11</i>	18.70 X	
7 FRONT GRILLE BASE	268.80	1 PC <i>CM</i>	268.80 ✓	
8 FRONT GRILLE LOWER CHROME	202.80	1 PC <i>11</i>	202.80 X	
9 FRONT GRILLE OUTER GARNISH WITH CHROME	224.10	1 PC <i>11</i>	224.10 X	
10 FRONT GRILLE LOGO	30.00	1 PC <i>11</i>	30.00 X	
11 FRONT GRILLE TOP GARNISH	24.20	1 PC <i>11</i>	24.20 X	
12 FRONT GRILLE TOP GARNISH CLIPS	3.90	5 PC <i>11</i>	19.50 X	
13 FRONT GRILLE LOGO CLIPS	6.80	2 PC <i>11</i>	13.60 X	
14 HEADLAMP UNIT - LH/RH	795.00	2 PC <i>11</i>	1,590.00 X	
15 HEADLAMP LOWER RETAINER - LH/RH	33.40	2 PC <i>11</i>	66.80 X	
16 BONNET	586.90	1 PC <i>100%</i>	586.90 ✓	
17 BONNET INSULATOR CLIPS	3.90	6 PC <i>11</i>	23.40 X	
18 BONNET LOCK	111.60	1 PC <i>50%</i>	111.60 X	
19 BONNET RUBBER (INNER) - LH/RH	22.30	2 PC <i>11</i>	44.60 X	
20 BONNET RUBBER (OUTER) - LH/RH	22.30	2 PC <i>11</i>	44.60 X	
			4,435.80	
Less 20%			-887.16	3,548.64

Special Net

Progressive Car Care Pte Ltd

Blk 3022A Ubi Road 1 #01-45/46 Singapore 408716

TEL: 6741 5336 FAX: 6741 7208

Email: claims@procarcare.com.sg

GST REG NO: 201006949C Company Reg No: 201006949C

21	FRONT NUMBER PLATE WITH CASING	45.00	1 PC	50	45.00	X	
							45.00
Labour							
22	TO KNOCK OUT DENTS, REMOVE, REPLACE ACCIDENT PORTIONS	550.00	1 PC	550.00	380		
23	TO RESPRAY PAINT ON ACCIDENT PORTIONS	600.00	1 PC	600.00	500		
24	TO CHECK WIRING	30.00	1 PC	30.00	20		
							1,180.00

Total	4,773.64
Add GST @ 9%	429.63
Total Amount Payable SGD	5,203.27

SINGAPORE DOLLAR FIVE THOUSAND TWO HUNDRED THREE AND CENTS TWENTY SEVEN ONLY

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) before resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

P-1813-4
202
12/10/22
900
21/10/22
202
1688

For Progressive Car Care Pte Ltd

AUTHORISED SIGNATURE