

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/0581/2024/KS
DATE : 30-Jul-24
WIP : 25274

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 1/8/2024

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Motor Claims Dept

OWNER'S NAME : MR CHAI KHAI BOON
ADDRESS : 109 PETIR ROAD
#18-21
SINGAPORE 678276

TELEPHONE : HP +65 97251327
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO : 1800102739-04
VEHICLE NO : SMD 2748 M
MODEL CODE : AUDI Q2 1.0 TFSI S TRONIC
MODEL YEAR : 13/8/2018
ENGINE NO : CHZ 959033
CHASSIS NO : WAUZZZGA4JA096305
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 29-Jul-24
PLACE OF ACCIDENT : HILLV2, 4 HILLVIEW RISE 667979, HEADING OUT FROM
CARPARK TO MAIN ROAD

55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SMD 2748 M


S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR AND HEADLIGHT WASHER.	S/N \$ 360.00	X
2	TO REMOVE AND TRANSFER RHS FRONT DOOR MULTI-LOCK SYSTEM AND POWER WINDOW DEVICES. INSPECT FOR DAMAGES.	S/N \$ 400.00	X
3	TO REMOVE AND TRANSFER FRONT BUMPER. TO DISMANTLE AND RENEW RHS FRONT FENDER AND RHS FRONT DOOR. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$ 3,200.00	500
4	TO RESPRAY RHS FRONT FENDER AND RHS FRONT DOOR.	\$ 2,300.00	1100
6	TO RENEW RIM AND CARRY OUT WHEEL ALIGNMENT.	S/N \$ 280.00	/
7	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$ 292.00	/
TOTAL LABOUR CHARGES		: \$ 6,832.00	

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMD 2748 M

S/N	PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES	
			S/NETT	REMARKS
1	FRONT FENDER - RH	1 \$	1,365.00	X R
2	FRONT FENDER ATTACHMENT PARTS - RH	1 \$	47.00	X nn
3	FRONT FENDER BRACKET - RH REAR	1 \$	20.00	X nn
4	FRONT FENDER BRACKET - RH CENTER	1 \$	62.00	X nn
5	FRONT FENDER BRACKET - RH FRONT	1 \$	20.00	X nn
6	FRONT FENDER RIVET - RH	6 \$	26.00	X nn
7	FRONT FENDER BRACE - RH	1 \$	67.00	X nn
8	FRONT FENDER CLOSING ELEMENT - RH	1 \$	42.00	X nn
9	FRONT FENDER INSULATION - RH	1 \$	129.00	X nn
10	FRONT FENDER SEAL - RH UPPER	1 \$	47.00	X nn
11	FRONT FENDER SEAL - RH LOWER	1 \$	56.00	X nn
12	FRONT HEADLIGHT BRACKET - RH	1 \$	236.00	X nn
13	FRONT WHEEL HOUSING LINER - RH	1 \$	67.00	X nn
14	FRONT WHEEL HOUSING LINER ATTACHMENT PART	1 \$	802.00	320.40 /
15	FRONT WHEEL ARCH COVER - LH / RH	1 \$	802.00	X R
16	FRONT DOOR - RH	1 \$	3,152.00	X nn
17	FRONT DOOR ATTACHMENT PARTS - RH	1 \$	3,152.00	X nn
18	FRONT DOOR CATCH - RH	1 \$	300.00	X nn
19	FRONT DOOR HINGE UPPER PART - RH UPPER	1 \$	53.00	X nn
20	FRONT DOOR HINGE LOWER PART - RH UPPER	1 \$	60.00	X nn
	FRONT DOOR HINGE UPPER PART - RH LOWER	1 \$	55.00	X nn
SUB TOTAL SPARE PARTS		:	\$ 9,758.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.




55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMD 2748 M

S/N	PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES	
			S/NETT	REMARKS
21	FRONT DOOR HINGE LOWER PART - RH UPPER	1	\$ 60.00	X nn
22	FRONT DOOR LOWER COVER - RH	1	\$ 304.00	/ CUT 242.8
23	FRONT ALUMINIUM RIM - RH	1	\$ 1,150.00	/ CUT 920
24	FRONT ALUMINIUM RIM RUBBER VALVE - RH	1	\$ 5.00	/ AC 3.28
25	SUNDRIES		\$ 500.00	/ x nn
TOTAL SPARE PARTS		:	\$ 11,777.00	
TOTAL LABOUR CHARGES		:	\$ 6,832.00	
GRAND TOTAL		:	\$ 18,609.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST
LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.



55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME	:	Steve (LKK)	90 - M1 AL
SURVEYED DATE	:	1/8/24, 10.00am	Excess - ?
AUTHORISED DATE	:		P/P
EXCESS COST	:		4 BL sy
LIABILITY	:		5 dgs
REMARKS	:		

PLEASE NOTE :

THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY.

FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,
 PREMIUM AUTOMOBILES PTE LTD

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature: _____
 Date: _____

JOHNNY BOO
 BODY REPAIR MANAGER

ALLAN WU
 CLAIMS CONSULTANT