

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315 Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS	INCOME INSURAN		Ref:	CS/INC24060080/Tgh3m4
	75 BRAS BASAH R		Date:	16/08/2024
	INCOME CENTRE	SINGAPORE 189557	Code:	INC
1.	Policy Particulars :- THIRD PARTY CLAIM			
	Insured Veh.	SFL 3970X	Veh. Inspected	SFH 4866D
	Policy No.	-	Coverage	0
	Claim No.	MT/1280162-002	Excess	\$0.00
	Assign From	AMANDA CHOOI	Assign Date	13/06/2024
2. Vehicle Details				
	Make & Model	MAZDA 5	C.C	1999
	Engine No.	LF10577659	Year of Reg.	26/09/2008
	Chassis No.	JM6CR10F280306928	Colour	SILVER
	Odometer	305091 KM	Steering	IN ORDER
	Brakes	IN ORDER	General	GOOD
	Modification(s)	RIMS: SPORTS RIM		
3. Conditions of Tyres				
		Size	Make	Balance (mm)
	R/H Front Tyre	205/55R16	PIRELLI	6
	L/H Front Tyre	205/55R16	PIRELLI	6
	R/H Rear Tyre	205/55R16	PIRELLI	6
	L/H Rear Tyre	205/55R16	PIRELLI	6
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR O/S PORTION.				
DAMAGES SEE DETAILS.				
5.	General Information			
	Accident Date	01/06/2024	Inspection Date	13/06/2024 (12:00)
	Survey held at JL PERFECT AUTOWORK PTE LTD 8 KAKI BUKIT AVENUE 4, #08-09, PREMIER @ KAKI BUKIT, SINGAPORE 415875			
5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR: 3 Working Days				