



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,  
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No.  
19-9607198-R

## Affiliated to Federation Internationale Des Experts En Automobile

MS MS FIRST CAPITAL INSURANCE LTD	Ref:	CS/FCI24070493/Evp3e2
16 RAFFLES QUAY	Date:	19/08/2024
#42-01 HONG LEONG BUILDING	Code:	FCI2
SINGAPORE 048581		

### 1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SHD 7258L	Veh. Inspected	SHD 6499P
Policy No.	D-24101861MFCT	Coverage	0
Claim No.	D24006614MFCT	Excess	\$0.00
Assign From	JOANNE	Assign Date	30/07/2024

### 2. Vehicle Details

Make & Model	TOYOTA PRIUS	C.C	1798
Engine No.	2ZRS104511	Year of Reg.	03/11/2017
Chassis No.	JTDKB3FU403574274	Colour	MAROON
Odometer	701321 KM	Steering	IN ORDER
Brakes	IN ORDER	General	GOOD
Modification(s)	RIMS: SPORTS RIM		

### 3. Conditions of Tyres

	Size	Make	Balance (mm)
R/H Front Tyre	195/65 R15	GREENTRAC	5
L/H Front Tyre	195/65 R15	GREENTRAC	5
R/H Rear Tyre	195/65 R15	GREENTRAC	5
L/H Rear Tyre	195/65 R15	GREENTRAC	5

### 4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE N/S BODY.

DAMAGES SEE DETAILS.

### 5. General Information

Accident Date	27/07/2024	Inspection Date	31/07/2024
Survey held at	STRIDES PREMIER AUTOMOTIVE SERVICES PL - 23 CHANGI SOUTH AVE 2 SINGAPORE 486443		

### 5a. Remarks

A) DAMAGES CONSISTENT TO ACCIDENT REPORT.  
B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.  
C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

### 5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: 6 Working Days