



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
LIBERTY INSURANCE PTE LTD ONE RAFFLES QUAY #25-01 NORTH TOWERSINGAPORE 048583 ATTN: ANDY SEAH			Ref: CS/LIP24070495/Aqh3m4(N) Date: 21/01/2025 Code: LIP	
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SMN 6045D	Veh. Inspected	SGU 5986D
	Policy No.		Coverage (\$)	0.00
	Claim No.	BVS24/0518	Excess (\$)	0.00
	Assign From	ANDY SEAH	Assign Date	30/07/2024
2. Vehicle Particulars & Condition				
	Make & Model	SUBARU FORESTER	c.c	1998
	Engine No.	HIDDEN	Year of Reg.	
	Chassis No.	JF1SJGK85GG069231	Colour	BLACK
	Odometer	205424 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	SPORTS RIM
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	225/55R18	TOYO	6 mm
	L/H Front Tyre	225/55R18	TOYO	6 mm
	R/H Rear Tyre	225/55R18	TOYO	6 mm
	L/H Rear Tyre	225/55R18	TOYO	6 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE FRONT N/S AND FRONT PORTION. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	24/07/2024	Inspection Date	31/07/2024
	Survey held at	CHIN CHUAN GARAGE BLK 3006 UBI ROAD 1 #01-338 SINGAPORE 408700		
5a. Remarks				
	A)REGISTRATION DATE: 31 MAR 2016 B)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. C)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		4 Working Days	