

(08/11/13) Wef

ASS. REC. BY:

REF:

CS/FC124070499/Rnp3

8022

## ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_

Estimated Cost: \_\_\_\_\_

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SHJ 82125

at Workshop m/s PORNO

of PANDAN CRESCENT

Insured: FC12

Policy No. \_\_\_\_\_

Claims No. \_\_\_\_\_


Sum Insured: \_\_\_\_\_

Excess: \_\_\_\_\_

(Client's Record)

Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its  
repair at the time of inspection.

Bal. or Market Value: 167K

IDAC Accident Rpt: \_\_\_\_\_

Consistent?: Yes or No

GIA / PR Seen: \_\_\_\_\_

Consistent?: Yes or No

Est. Repairs: \_\_\_\_\_

days

Res.: Yes or No

Lum Sum: \_\_\_\_\_

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: \_\_\_\_\_

Person Contacted: \_\_\_\_\_

Vehicle: IN / OUT

Veh No: SHJ 82125

Yr Regn: 2013 / MAR

Type: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: TOYOTA VELL FIRE 21524-6 cc 2493

Colour: BLACK

AC: Insured / Std / NI / NA

Sp. Reading: 12179

T/Radio: Insured / Std / NI / NA

Eng/No: \_\_\_\_\_

C/No: AH1300214414

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 235/50R18

R: \_\_\_\_\_

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 6 mm

R/Bal. 6 mm

L/Bal. 6 mm

L/Bal. 6 mm

D.O.A. 27/07/24

D.O.I. 31/07/24

Survey held at PANDAN CRESCENT

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

REPAIR LIMIT - 107K

We will be advising our principal a cost of repair P/P \$67,078.14 /- with 14 days  
(red, \$20267.9, 23%)

Date/Time, File Pass to?

☐ : Prell. Report  
☐ : Final Report

Days Of Repair: 14

Resurvey No. of Trip: \_\_\_\_\_

Survey Fee: \_\_\_\_\_

Transportation: \_\_\_\_\_

1)

Date/Time, File Return to?

2)

Add Fee: \_\_\_\_\_

Site Insp (\$ \_\_\_\_\_)

Interview (\$ \_\_\_\_\_)

Tech. Invs (\$ \_\_\_\_\_)

Weekend (\$ \_\_\_\_\_)

S + RS \$ \_\_\_\_\_

Photos

Others

TOTAL

Report Format: \_\_\_\_\_

Lump Sum / I.B.I: (\$ \_\_\_\_\_)



# Borneo Motors



# TOYOTA

Inchcape

Co. Reg No. : 196700086Z  
GST Reg No. : MR-8500000-9  
No. 2 PANDAN CRESCENT  
SINGAPORE 128462, Tel no.: 6631 1188

## ESTIMATE

Account Details	Account No.	Customer Details
MS First Capital Insurance Ltd 16 Raffles Quay #42-01 Hong Leong Building Singapore 048581 Attn: Motor Claims Dept	S1000005 / ICFIC1	Ms Tong Sui Min Frances 1 Mount Echo Park Singapore 248765 Mobile: 96869032
	Document No. 0	
	Document Date 29/07/2024	

Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks
2018	AGH30R	NFXLK S4	21/03/2019	SGJ8212S	0	31883	79/DS/SGJ8212S

Chassis No.	Engine No.	Terms	SA / Counter	Vehicle In	Collected On
AGH300214474	2ARJ211514	60	Ong Wen Hong	--/--/----	0.00 --/--/---- 0.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
1	Z	BP-SUNDRY TP INS:MS FIRST CAPITAL TP VEH:SHD7258L DATE OF ACC:27/07/2024 NUMBER OF REPAIR DAYS: SURVEY BY:				50 100.00
2	Z	BP-SLANT SUPPLY SEALANT (NETT)				300 400.00
3	B	BP-LAB2 TO REPLACE AND REPAIR ACCIDENT DAMAGED P ARTS				7128 8712.00
4	B	BP-RES2 TO RESPRAY ALL ACCIDENT AFFECTED AREAS				3936 5248.00
5	B	BP-LAB2 TO CHECK WIRING SYSTEM				134.64
6	B	BP-LAB2 TO DRILL HOLE AND INSTALL FRONT & REVERS E SENSOR				396.00
7	B	BP-LAB2 TO REMOVE INTERIOR UPHOLSTERY TO FAC REP AIR				396.00
8	B	BP-LAB2 TO REMOVE AND TRANSFER DOOR COMPONENT TO NEW DOOR				792.00
9	B	BP-LAB2 TO REMOVE AND RE-INSTALL REAR SEAT & SID E TRIMS				396.00
10	B	BP-MECH2 TO REMOVE AND REPLACE FRONT SUSPENSION				? 792.00
11	B	BP-MECH2 TO REMOVE AND INSTALL FUEL TANK				792.00

For & on behalf of	Customer's Signature	Charge Summary	Total
Borneo Motors (Singapore) Pte Ltd	Please acknowledge receipt of vehicle	Parts	Less
		Labour	
		Sublet	Amount Due
		Lubrication/Fluid	
		Others	



# Borneo Motors



# TOYOTA

Inchcape

Co. Reg No. : 196700086Z  
GST Reg No. : MR-8500000-9  
No. 2 PANDAN CRESCENT  
SINGAPORE 128462, Tel no.: 6631 1188

## ESTIMATE

Account Details	Account No.	Customer Details
MS First Capital Insurance Ltd 16 Raffles Quay #42-01 Hong Leong Building Singapore 048581 Attn: Motor Claims Dept	S1000005 / ICFIC1	Ms Tong Sui Min Frances 1 Mount Echo Park  Singapore 248765  Mobile: 96869032
	Document No. 0	
	Document Date 29/07/2024	

Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks
2018	AGH30R	NFXLK S4	21/03/2019	SGJ8212S	0	31883	79/DS/SGJ8212S
Chassis No.	Engine No.	Terms	SA / Counter	Vehicle In	Collected On		
AGH300214474	2ARJ211514	60	Ong Wen Hong	--/--/----	0.00	--/--/----	0.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
12	B	BP-MECH2 TO REPLACE RIM AND WHEEL BALANCING				158.40 ✓
13	B	BP-MECH2 TO CONDUCT WHEEL ALIGNMENT				198.00 ✓
14	B	BP-MECH2 TO CONDUCT ADJUSTMENT ON BLIND SPOT SENS OR				198.00 ✓
15	B	BP-ECU2 TO RESET ECU AND REPROGRAMME				198.00 ✓
16	B	BP-WS2 TO REMOVE AND INSTALL REAR QUARTER GLASS LH				396.00 ✓
17	S	BP-SUBLET TO SUPPLY SOLAR FILM FOR REAR QUARTER GL ASS				230.00 ✓
18	1	T42611-58330 WHEEL, DISC <i>sun</i>	2.00	3456.30		6912.60
19	2	T42603-48140 ORNAMENT SUB-ASSY <i>sun</i>	2.00	56.10		112.20
20	3	L43212-78010 KNUCKLE, STEERING, <i>h???</i>	1.00	1032.00		1032.00
21	4	T43550-28030 HUB & BEARING ASSY, <i>h???</i>	1.00	928.20		928.20
22	5	T45510-58060 GEAR ASSY, STEERING <i>h???</i>	1.00	2732.00		2732.00
23	6	T45047-29195 END SUB-ASSY, TIE <i>h???</i>	1.00	285.80		285.80
24	7	T47782-28210 COVER, DISC BRAKE <i>h???</i>	1.00	139.90		139.90
25	8	T48069-28140 ARM SUB-ASSY, <i>h???</i>	1.00	1246.40		1246.40
26	9	T48820-42030 LINK ASSY, FR <i>h???</i>	1.00	228.10		228.10
27	0	T51201-28281 CROSSMEMBER <i>h???</i>	1.00	3750.90		3750.90
28	1	T52119-58650 C0 COVER, FR BUMPER <i>sun</i>	1.00	3365.30		3365.30

For & on behalf of	Customer's Signature	Charge Summary	Total
Borneo Motors (Singapore) Pte Ltd			
	Please acknowledge receipt of vehicle	Parts Labour Sublet Lubrication/Fluid Others	Less Amount Due

hchcape

Co. Reg No. : 196700086Z  
GST Reg No. : MR-8500000-9  
No. 2 PANDAN CRESCENT  
SINGAPORE 128462, Tel no.: 6631 1188

## ESTIMATE

Account Details	Account No.	Customer Details
MS First Capital Insurance Ltd 16 Raffles Quay #42-01 Hong Leong Building Singapore 048581 Attn: Motor Claims Dept	S1000005 / ICFIC1	Ms Tong Sui Min Frances 1 Mount Echo Park Singapore 248765 Mobile: 96869032
	Document No. 0	
	Document Date 29/07/2024	

Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks
2018	AGH30R	NFXLK S4	21/03/2019	SGJ8212S	0	31883	79/DS/SGJ8212S
Chassis No.	Engine No.	Terms	SA / Counter	Vehicle In	Collected On		
AGH300214474	2ARJ211514	60	Ong Wen Hong	--/--/----	0.00	--/--/----	0.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
29	2	T52421-58020 PAD, FR BUMPER	2.00	95.60		191.20
30	3	S52161-0K040 PIECE, RR BUMPER	10.00	5.80		58.00
31	4	T52116-58090 SUPPORT, FR BUMPER	1.00	105.20		105.20
32	5	T52040-58210 COVER ASSY, FR	1.00	1696.00		1696.00
33	6	T89348-33400 RETAINER, ULTRASONIC	1.00	21.40		21.40
34	7	T89348-58290 CO RETAINER, ULTRASONIC	2.00	28.30		56.60
35	8	S52161-0K040 PIECE, RR BUMPER	6.00	5.80		34.80
36	9	T52156-58030 SUPPORT, RR BUMPER	1.00	149.80		149.80
37	0	T52156-58040 SUPPORT, RR BUMPER	1.00	157.10		157.10
38	1	T53802-58160 FENDER SUB-ASSY, FR	1.00	1998.70		1998.70
39	2	T53883-58010 SEAL, FR FENDER, LH	1.00	136.80		136.80
40	3	T53836-58050 BRACE, FR FENDER TO	1.00	64.20		64.20
41	4	T53806-58110 SHIELD SUB-ASSY, FR	1.00	361.40		361.40
42	5	T61602-58110 PANEL SUB-ASSY, FR	1.00	2339.00		2339.00
43	6	T65638-58041 LINER, RR WHEEL	1.00	359.90		359.90
44	7	T62720-58250 WINDOW ASSY, FR	1.00	973.30		973.30
45	8	T67002-58080 PANEL SUB-ASSY, FR	1.00	3204.30		3204.30
46	9	T75924-58010 TAPE, BLACK OUT, FR	1.00	54.40		54.40
47	0	T75922-58010 TAPE, BLACK OUT, FR	1.00	30.40		30.40
48	1	T68720-12151 HINGE ASSY, FR DOOR, FR	1.00	135.40		135.40

For & on behalf of	Customer's Signature	Charge Summary	Total
Borneo Motors (Singapore) Pte Ltd			
	Please acknowledge receipt of vehicle	Parts Labour Sublet Lubrication/Fluid Others	Less Amount Due



inchcape  
Co. Reg No. : 196700086Z  
GST Reg No. : MR-8500000-9  
No. 2 PANDAN CRESCENT  
SINGAPORE 128462, Tel no.: 6631 1188

**ESTIMATE**

Account Details	Account No.	Customer Details
MS First Capital Insurance Ltd 16 Raffles Quay #42-01 Hong Leong Building Singapore 048581 Attn: Motor Claims Dept	S1000005 / ICFIC1	Ms Tong Sui Min Frances 1 Mount Echo Park Singapore 248765 Mobile: 96869032
	Document No. 0	
	Document Date 29/07/2024	

Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks
2018	AGH30R	NFXLK S4	21/03/2019	SGJ8212S	0	31883	79/DS/SGJ8212S
Chassis No.	Engine No.	Terms	SA / Counter	Vehicle In	Collected On		
AGH300214474	2ARJ211514	60	Ong Wen Hong	--/--/----	0.00	--/--/----	0.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
49	2	T68740-12120 HINGE ASSY, FR DOOR, ?	1.00	153.00		153.00
50	3	T67004-58080 PANEL SUB-ASSY, Side ?	1.00	3256.70		3256.70
51	4	T67865-58071 WEATHERSTRIP, CTR ?	1.00	203.80		203.80
52	5	T84260-58041 SENSOR ASSY, POWER ?	1.00	1211.10		1211.10
53	6	T75752-58011 MOULDING, FR DOOR ?	1.00	60.00		60.00
54	7	T75756-58030 MOULDING, FR DOOR ?	1.00	142.90		142.90
55	8	T75762-58011 MOULDING, RR DOOR ?	1.00	128.40		128.40
56	9	T75742-58030 MOULDING, RR DOOR ?	1.00	191.10		191.10
57	0	T75764-58010 MOULDING, RR DOOR ?	1.00	108.50		108.50
58	1	T75766-58030 MOULDING, RR DOOR ?	1.00	174.20		174.20
59	2	T65632-58020 PLATE, RR WHEEL ?	1.00	75.50		75.50
60	3	T76904-58060 C0 MUDGUARD SUB-ASSY, ?	1.00	1191.80		1191.80
61	4	T76906-58060 C0 MUDGUARD SUB-ASSY, ?	1.00	1123.00		1123.00
62	5	T76902-58050 C0 MUDGUARD SUB-ASSY, ?	1.00	281.20		281.20
63	6	T76908-58090 C0 MUDGUARD SUB-ASSY, ?	1.00	414.10		414.10
64	7	T81185-58650 UNIT, HEADLAMP ?	1.00	9008.90		9008.90
65	8	T48520-80426 ABSORBER SET, SHOCK, ?	1.00	660.00		660.00

*Handwritten notes:*  
 2 Asst  
 Ho 90010068  
 14 lamp  
 31/07/24  
 Reimg by  
 paint

For & on behalf of Borneo Motors	<b>LKK Auto Consultants</b> hence notify the Repairer of the following: • To display damaged part(s) during resurvey • Parts prices are subject to confirmation • Third party survey is on a "Without Prejudice" basis • No illegal modification(s) is allowed • Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company	Customer's Signature	Charge Summary	Total 70,782.54 GST 9.00% 6,370.43
Acknowledged by Repairer Signature: Date:		Please acknowledge receipt of vehicle Parts 51,245.50 Labour 19,307.04 Sublet 230.00 Lubrication/Fluid 0.00 Others 0.00	Less 0.00 Amount Due 77,152.97	

> Back to OneMotoring

## Enquire PARF/COE Rebate for Registered Vehicle

<b>Vehicle Owner Particulars</b>	
Owner ID Type:	Singapore NRIC
Owner ID:	802Z
<b>Vehicle Details</b>	
Vehicle No.:	SGJ82125
Vehicle to be Exported:	No
Intended Deregistration Date:	01 Aug 2024
Vehicle Make:	TOYOTA
Vehicle Model:	VELLFIRE 2.5Z G-EDITION CVT
Primary Colour:	Black
Manufacturing Year:	2018
Engine No.:	2ARJ211514
Chassis No.:	AGH300214474
Maximum Power Output:	134.0 kW (179 bhp)
Open Market Value:	\$50,226.00
Original Registration Date:	21 Mar 2019
First Registration Date:	21 Mar 2019
Transfer Count:	1
Actual ARF Paid:	\$62,407.00
<b>Intended PARF Rebate Details</b>	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	20 Mar 2029
PARF Rebate Amount:	\$43,684.00
<b>Intended COE Rebate Details</b>	
COE Expiry Date:	20 Mar 2029
COE Category:	E - Open - all except motorcycle
COE Period(Years):	10
QP Paid:	\$33,689.00
COE Rebate Amount:	\$15,612.00
<b>Total Rebate Amount:</b>	<b>\$59,296.00</b>
<b>Message</b>	
You will not be eligible for any COE rebate from the current COE (including unused COE from any lay-up period/s), if you renew your COE.	

The information contained herein is correct as at 01 Aug 2024

OK

Toyota Vellfire 2.5A Z G-Edition

**\$163,800** Instalment \$2,093/mth









 Shortlist

 Get Warranty

 Loan Calculator



Overview Financial Leasing Photo Research

Depreciation	 \$29,640 / year
Reg. Date	02-Jan-2019 (4yrs 5mths COE left)
Manufactured	 2018
Mileage	79,000 km (14.1k / year)
Transmission	Auto
Engine Cap	2,493 cc
Road Tax	 \$1,792 / year
Power	134.0 kW (179 bhp)
Curb Weight	 2,030 kg
COE	 \$30,851
OMV	 \$51,909
ARF	 \$65,437
Dereg Value	 \$59,428 as of today