



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No.
19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MS UNITED OVERSEAS INSURANCE LTD
146 ROBINSON ROAD
#02-01 UOI BUILDING SINGAPORE 068909

Ref: CS/UOI24070501/Unp3

Date: 08/10/2024

Code: UOI2

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SLV 1329M	Veh. Inspected	FBJ 6092T
Policy No.	-	Coverage	0
Claim No.	M12D00022408	Excess	\$0.00
Assign From	JOEY TAY	Assign Date	31/07/2024

2. Vehicle Details

Make & Model	YAMAHA TMAX 500	C.C	499
Engine No.	J406E068191	Year of Reg.	13/09/2010
Chassis No.	JYASJ061000047319	Colour	MAROON
Odometer	135581 KM	Steering	IN ORDER
Brakes	IN ORDER	General	GOOD
Modification(s)	RIMS: SPORTS RIM		

3. Conditions of Tyres

	Size	Make	Balance (mm)
R/H Front Tyre	120/70-15	PIRELLI	6
L/H Front Tyre			
R/H Rear Tyre	160/60R15	PIRELLI	6
L/H Rear Tyre			

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR O/S PORTION AND N/S BODY.

DAMAGES SEE DETAILS.

5. General Information

Accident Date	26/07/2024	Inspection Date	31/07/2024
Survey held at	ERZAT LEE MOTOR TRADING PTE LTD 25 KAKI BUKIT ROAD 4, #03-37, SYNERGY @ KB, SINGAPORE 417800		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: 3 Working Days