

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933
TEL: 6256 3561 FAX: 6256 4315
Reg. No: 199607198R GST Reg. No.
19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MS INCOME INSURANCE LTD	Ref:	CS/INC24060082/Eqh3e2
75 BRAS BASAH ROAD	Date:	16/07/2024
INCOME CENTRE SINGAPORE 189557	Code:	INC

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	YR 362P	Veh. Inspected	YM 8025L
Policy No.	-	Coverage	0
Claim No.	MT/1274817-005	Excess	\$0.00
Assign From	SHAFAWATI BINTE MD RABU	Assign Date	13/06/2024

2. Vehicle Details

Make & Model	ISUZU NPR85LU4Y	C.C	2999
Engine No.	4JJ1580407	Year of Reg.	14/02/2008
Chassis No.	JAANPR85L87100066	Colour	WHITE
Odometer	614563 KM	Steering	IN ORDER
Brakes	IN ORDER	General	GOOD
Modification(s)	RIMS: STANDARD ALLOY RIM		

3. Conditions of Tyres

	Size	Make	Balance (mm)
R/H Front Tyre	7.00 R16	GT RADIAL	5
L/H Front Tyre	7.00 R16	GT RADIAL	5
R/H Rear Tyre	7.00 R16	GT RADIAL	5
L/H Rear Tyre	7.00 R16	GT RADIAL	5

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE FRONT N/S PORTION.

DAMAGES SEE DETAILS.

5. General Information

Accident Date	25/04/2024	Inspection Date	13/06/2024 (02:23PM)
Survey held at	RYDER AUTO PTE LTD 2 KAKI BUKIT AVE 2 #02-19/22 KAKI BUKIT AUTOHUB SINGAPORE 417921		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: 5 Working Days