

LEONG AUTO PTE LTD

160 Sin Ming Drive, Sin Ming AutoCity, #02-13, Singapore 575722
Tel: 62666448 Fax: 62666358 Email: Sales@leongauto.com.sg
Business Registration No. 201312846W
GST Registration No. 201312846W

Not Notified
11 Ppm &
Running After Pains
3-4 days

ESTIMATE

Date: 31/7/2024
DOA: 27/7/2024

Vehicle No: SJZ1951T
Make & Model: Honda Civic EK9

S/N	Qty	Item Description	Parts Price	Surveyor
1	1	Rear Bumper	\$ 1,348.50	
2	1	Rear Bumper Side Retainer	\$ 251.50	x
3	2	Rear Bumper Parking Sensor	\$ 519.00	?
4	2	Rear Tail Lamp	\$ 525.30	4
5	2	Rear Tail Gate Tail Lamp	\$ 128.40	x
			\$ 2,372.70	
		Less 20%	\$ 474.54	
			\$ 1,898.16	

Special Nett Items

1		Sundries	\$ 50.00	x
2	1	Rear Carbon Fibre Tail Gate	\$ 3,000.00	—
3	1 set	Rear Bumper Clips	\$ 50.00	—
4	1 set	Rear No. Plate with Garnish	\$ 150.00	* 25in
5	1 set	Rear Reverse Camera	\$ 300.00	?
6	1	Rear Exhaust Assembly	\$ 4,500.00	x
		1 set Rear Reverse Sensor - \$300 X	\$ 8,050.00	
		Total Parts	\$ 9,948.16	

S/N	Labour Description	Amount	Amount
1	Labour for panel beating, cut, weld, straighten and replace rear damaged parts.	\$ 1,600.00	400
2	To putty and spray painting rear portion.	\$ 1,200.00	200
3	To check rear lighting and wiring.	\$ 80.00	20
4	To remove and install rear tail gate lock mechanism.	\$ 120.00	50
5	To apply anti rust proofing to rear affected area.	\$ 250.00	x
6	To remove and install rear reverse camera.	\$ 150.00	30
7	To remove and install rear reverse sensor.	\$ 150.00	50
8	To remove & refit tail gate component to replace tail gate, check & re-adjust the close gap and alignment and water seepage	\$ 120.00	x
	Total labour :	\$ 3,670.00	

Total parts :

Total labour :

Total repair cost : (Before GST)

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation

- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

\$ 9,948.16
\$ 3,670.00
\$ 13,618.16