

(08/11/13) wef

ASS. REC. BY: Marcus

REF:

CS/CT/24080014/Unp3**ASSIGNMENT**

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SFF 8772Aat Workshop m/s PA ubi Jpn.

of _____

Insured: SLW 9784K

Policy No. _____


Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.Bal. or Market Value: 840k.

IDAC Accident Rpt: _____ Consistent?: Yes or No

GIA / PR Seen: _____ Consistent?: Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

LTA \$13614
Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: SFF 8772A Yr Regn: 20/12/08Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /Truck / Trailer or CAMake: Zeysa Noah c.c. 1988Colour: White A/C: Insured / Std / NI / NASp. Reading: 337807 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: ZRR 700146521Gen. Cond: Good / Fair / Poor / BurntSteering: Inorder / Jammed / Leaked / Burnt orBrake: Inorder / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim orTyre Size: F: 215/60 R16

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front: 6 Rear: 6

R/Bal. _____ mm R/Bal. _____ mm

L/Bal. 6 mm L/Bal. 6 mmD.O.A. 31/07/24 D.O.I. 12/08/24

Survey held at _____

Des. of Damages: Frnt / Rear / O/S / N/S / U/C / Rooftop orRear

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction Dep. 10/12/2028Che unch / 19-10-2028

Date/Time, File Pass to?

☐ : Preli. Report

1)

☐ : Final Report

Date/Time, File Return to?

2)

Days Of Repair: _____

Resurvey No. of Trip: _____

Add Fee: ☐ : Site Insp (\$ _____)☐ : Interview (\$ _____)☐ : Tech. Invs (\$ _____)☐ : Weekend (\$ _____)

Survey Fee:

Transportation:

S + RS, \$ _____

Photos

Others

TOTAL

Report Format :

Lump Sum / I.B.I: (\$ _____)

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	789H
Vehicle Details	
Vehicle No.:	SFF8772A
Vehicle to be Exported:	Yes
Intended Deregistration Date:	31 Jul 2024
Vehicle Make:	TOYOTA
Vehicle Model:	NOAH 2.0S A
Primary Colour:	White
Manufacturing Year:	2008
Engine No.:	3ZR4199321
Chassis No.:	ZRR700146521
Maximum Power Output:	105.0 kW (140 bhp)
Open Market Value:	\$24,231.00
Original Registration Date:	20 Oct 2008
First Registration Date:	20 Oct 2008
Transfer Count:	1
Actual ARF Paid:	\$24,231.00
Intended PARF Rebate Details	
PARF Eligibility:	Forfeited
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	19 Oct 2028
COE Category:	B - Car (1601cc & above)
COE Period(Years):	10
PQP Paid:	\$32,279.00
COE Rebate Amount:	\$13,614.00
Total Rebate Amount:	\$13,614.00
Message	
You will not be eligible for any COE rebate from the current COE (including unused COE from any lay-up period/s), if you renew your COE.	

The information contained herein is correct as at 31 Jul 2024

OK

Progressive Car Care Pte Ltd

Blk 3022A Ubi Road 1 #01-45/46 Singapore 408716

TEL: 6741 5336 FAX: 6741 7208

Email: claims@procarcare.com.sg

GST REG NO: 201006949C Company Reg No: 201006949C

CHINA TAIPING INSURANCE (SINGAPORE) PTE LTD

3 Anson Road

Springleaf Tower #16-00

Singapore 079909

Tel: 63896111

Fax: 6221033

Attn: Motor Claim Department

Your Ref No: TP 0724-8164

Claim Type: Third Party

Accident Date: 31 July 2024

TP Veh Reg No: SLW9754K

Estimate No: EST1511591

Date: 31 Jul 2024

Policy No: MT/00859097/03

Veh Reg No: SFF8772A

Make/Model: TOYOTA NOAH 2.0S A

Chassis No: ZRR700146521

Engine No: 3ZR4199321

Reg. Date: 20 Oct 2008

not Authorised
12/8/24

2/58
4 days
the phone team -

Estimate Repair Cost to Vehicle No: SFF8772A

Description	Unit Price	Quantity	List Price SGD	Amount SGD
List Price				
1 REAR BUMPER <i>DD/OE</i>	1,080.60	1 PC	1,080.60	—
2 REAR BUMPER SIDE RETAINER (INNER) - LH/RH <i>17</i>	108.60	2 PC	217.20	X
3 REAR BUMPER SIDE RETAINER (OUTER) - LH/RH <i>17</i>	98.70	2 PC	197.40	X
4 REAR BUMPER CLIPS <i>121</i>	5.50	10 PC	55.00	—
5 REAR BUMPER REFLECTOR - LH/RH <i>11</i>	80.60	2 PC	161.20	X
6 REAR BUMPER TOW COVER <i>11</i>	40.60	1 PC	40.60	X
7 TAILGATE <i>DD/OE</i>	2,875.60	1 PC	2,875.60	—
8 TAILGATE TOYOTA LOGO <i>121</i>	72.50	1 PC	72.50	—
9 TAILGATE OUTER CHROME <i>17</i>	850.40	1 PC	850.40	X
10 TAILGATE "S" WORDINGS <i>121</i>	71.50	1 PC	71.50	—
11 TAILGATE GLASS MOULDING <i>121</i> <i>211.50</i>	380.60	1 PC	380.60	—
12 TAILGATE WEATHERSTRIP <i>11</i>	480.40	1 PC	480.40	X
13 TAILGATE TOP LOCK <i>SVC</i>	560.00	1 PC	560.00	X
14 REAR END PANEL (OUTER) <i>DD/121</i>	688.40	1 PC	688.40	—
15 REAR END PANEL TOP GARNISH <i>17</i>	380.40	1 PC	380.40	X
16 REAR END PANEL TOP GARNISH SMALL LOCK <i>17</i>	60.50	1 PC	60.50	X
COVER				
			8,172.30	
		Less 25%	-2,042.90	6,129.40
Special Net				
17 SEALANT <i>Rear windscreen</i>	20.00	2 PC	<i>121</i> 40.00	—
18 SPONGE TAPE <i>Rear windscreen</i>	20.00	1 PC	<i>121</i> 20.00	—
19 REAR BUMPER SENSOR <i>SVC</i>	200.00	1 PC	200.00	X
				260.00
Labour				
20 TO KNOCK OUT DENTS, REMOVE, REPLACE ACCIDENT PORTIONS-	800.00	1 JOB	800.00	<i>600</i>
21 TO RESPRAY PAINT ON ACCIDENT PORTIONS-	800.00	1 JOB	800.00	<i>600</i>
22 TO CHECK WIRING- <i>refy</i>	30.00	1 JOB	30.00	<i>30</i>
23 TO REMOVE, REPLACE REAR BUMPER SENSOR-	150.00	1 JOB	150.00	<i>30</i>
24 TO REMOVE, REFIT GARNISH TO FACILITATE REPAIR-	80.00	1 JOB	80.00	<i>60</i>
25 TO TRANSFER TAILGATE FITTINGS-	80.00	1 JOB	80.00	<i>50</i>
26 TO TUFFKOTE-	90.00	1 JOB	90.00	<i>50</i>
27 TO REMOVE, REFIT REAR GLASS-	150.00	1 JOB	150.00	<i>120</i>
				2,180.00

Progressive Car Care Pte Ltd

Blk 3022A Ubi Road 1 #01-45/46 Singapore 408716

TEL: 6741 5336 FAX: 6741 7208

Email: claims@procarcare.com.sg

GST REG NO: 201006949C Company Reg No: 201006949C

Total	8,569.40
Add GST @ 9%	771.25
Total Amount Payable SGD	9,340.65

SINGAPORE DOLLAR NINE THOUSAND THREE HUNDRED FORTY AND CENTS SIXTY FIVE ONLY

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) before resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

For Progressive Car Care Pte Ltd

AUTHORISED SIGNATURE