



Borneo Motors

Inchcape

Co. Reg No. : 196700086Z
GST Reg No. : MR-8500000-9
No. 2 PANDAN CRESCENT
SINGAPORE 128462, Tel no.: 6631 1188



TOYOTA

ESTIMATE

Account Details			Account No.		Customer Details		
MS First Capital Insurance Ltd 16 Raffles Quay #42-01 Hong Leong Building Singapore 048581 Attn: Motor Claims Dept			S1000005 / ICFIC1		M/S Grab Rentals Pte. Ltd 3 Media Close #01-03/06 Singapore 138498 Work: 65703925		
			Document No. 0				
			Document Date 01/08/2024				
Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks
2018	ZVW40R	AWXEBW Q2	27/06/2018	SMC1932J	0	31991	67/TP/SMC1932J
Chassis No.		Engine No.	Terms	SA / Counter	Vehicle In		Collected On
JTDZS3EU80J028363		2ZR0B89973	60	Sam San Joi	--/--/----		0.00 --/--/---- 0.00
L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount	
1	Z	BP-GRAB-DS SUNDRIES - FLASH ARRIVE: DD/MM/YY 0000HR TP-SHF92H ACC DATE:31/07/2024 DRIVE IN:01/08/2024 DATE-IN:01/08/2024 DATE SURVEY: NO OF REPAIR DAYS: BY: AUTHORIZED ON:					100.00
2	S	BP-SUBLET REAR NUMBER PLATE					80.00
3	S	BP-SUBLET PHV STICKER					20.80
4	B	BP-LAB2 DRILL HOLE & INSTALL REAR REVERSE SENSOR					198.00
5	B	BP-LAB2 CHECK LIGHTING & CONDUCT WATER LEAK TEST					198.00
6	B	BP-LAB2 TRANSFER & INSTALL COMPONENTS TO NEW TAILGATE					594.00
7	B	BP-LAB2 REPLACE & INSTALL REAR TAILGATE GLASS					594.00
8	Z	BP-SLANT SUPPLY SEALANT (NETT)					200.00
9	B	BP-LAB2 REMOVE & INSTALL REAR COMPARTMENT CARPET ,GARNISH AND TRIMMING TO ASSIST REPAIR					396.00
10	B	BP-ECU2 TO RESET ECU AND REPROGRAMME					198.00
11	B	BP-LAB2 REPLACE REAR ACCIDENT DAMAGED PARTS STRAIGHTEN & ALIGN REAR ACCIDENT AFFECTED AREAS					3960.00
For & on behalf of Borneo Motors (Singapore) Pte Ltd			Customer's Signature		Charge Summary		Total
			Please acknowledge receipt of vehicle		Parts Labour Sublet Lubrication/Fluid Others		Less Amount Due

Company Copy



Borneo Motors

Inchcape

Co. Reg No. : 196700086Z
GST Reg No. : MR-8500000-9
No. 2 PANDAN CRESCENT
SINGAPORE 128462, Tel no.: 6631 1188



TOYOTA

ESTIMATE

Account Details	Account No.	Customer Details
MS First Capital Insurance Ltd 16 Raffles Quay #42-01 Hong Leong Building Singapore 048581 Attn: Motor Claims Dept	S1000005 / ICFIC1	M/S Grab Rentals Pte. Ltd 3 Media Close #01-03/06 Singapore 138498
	Document No. 0	Work: 65703925
	Document Date 01/08/2024	

Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks
2018	ZVW40R	AWXEBW Q2	27/06/2018	SMC1932J	0	31991	67/TP/SMC1932J
Chassis No.	Engine No.	Terms	SA / Counter	Vehicle In	Collected On		
JTDZS3EU80J028363	2ZR0B89973	60	Sam San Joi	--/--/----	0.00	--/--/----	0.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
12	B	BP-RES2 RESPRAY JOB ON REAR ACCIDENT AFFECTED AR EAS				3280.00
13	1	TREVSE-47006 24 BACK SENSOR 1G3 GREY ME	1.00	101.05		101.05
14	2	U52159-47912 COVER, RR BUMPER	1.00	855.40		855.40
15	3	U52576-47030 RETAINER, RR BUMPER	1.00	89.90		89.90
16	4	U52156-47010 SUPPORT, RR BUMPER	1.00	217.70		217.70
17	5	U52575-47030 RETAINER, RR BUMPER	1.00	89.90		89.90
18	6	U52155-47010 SUPPORT, RR BUMPER	1.00	217.70		217.70
19	7	K52161-0K040 PIECE, RR BUMPER	10.00	5.80		58.00
20	8	U52023-12240 REINFORCEMENT	1.00	334.00		334.00
21	9	U52016-47060 ARM SUB-ASSY, RR	1.00	243.00		243.00
22	0	U52015-47080 ARM SUB-ASSY, RR	1.00	243.00		243.00
23	1	U52023-12240 REINFORCEMENT	1.00	334.00		334.00
24	2	U52016-47060 ARM SUB-ASSY, RR	1.00	243.00		243.00
25	3	U52015-47080 ARM SUB-ASSY, RR	1.00	243.00		243.00
26	4	U76891-47040 SPOILER, RR NO.1	1.00	1175.80		1175.80
27	5	U75392-35220 RETAINER, OUTSIDE	10.00	5.60		56.00
28	6	U81910-47010 REFLECTOR ASSY,	1.00	83.40		83.40
29	7	U52591-47030 SEAL, RR BUMPER	1.00	124.60		124.60
30	8	U58307-47080 PANEL SUB-ASSY, BODY	1.00	1058.90		1058.90

For & on behalf of	Customer's Signature	Charge Summary	Total
Borneo Motors (Singapore) Pte Ltd	Please acknowledge receipt of vehicle	Parts Labour Sublet Lubrication/Fluid Others	Less Amount Due

Company Copy



Borneo Motors

Inchcape

Co. Reg No. : 196700086Z
GST Reg No. : MR-8500000-9
No. 2 PANDAN CRESCENT
SINGAPORE 128462, Tel no.: 6631 1188



TOYOTA

ESTIMATE

Account Details	Account No.	Customer Details
MS First Capital Insurance Ltd 16 Raffles Quay #42-01 Hong Leong Building Singapore 048581 Attn: Motor Claims Dept	S1000005 / ICFIC1	M/S Grab Rentals Pte. Ltd
	Document No. 0	3 Media Close #01-03/06 Singapore 138498
	Document Date 01/08/2024	Work: 65703925

Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks
2018	ZVW40R	AWXEBW Q2	27/06/2018	SMC1932J	0	31991	67/TP/SMC1932J
Chassis No.	Engine No.	Terms	SA / Counter	Vehicle In	Collected On		
JTDZS3EU80J028363	2ZR0B89973	60	Sam San Joi	--/--/----	0.00	--/--/----	0.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
31	9	U58308-47030 COVER SUB-ASSY, RR	1.00	757.90		757.90
32	0	U67935-47010 C0 PLATE, BACK DOOR	1.00	251.40		251.40
33	1	U67005-47460 PANEL SUB-ASSY, BACK	1.00	1692.80		1692.80
34	2	U67881-47030 WEATHERSTRIP, BACK	1.00	463.80		463.80
35	3	U68105-47170 GLASS SUB-ASSY, BACK	1.00	1675.30		1675.30
36	4	U56117-50140 DAM, WINDOW GLASS	1.00	40.10		40.10
37	5	T69350-28151 LOCK ASSY, BACK DOOR	1.00	571.50		571.50
38	6	U75310-47020 EMBLEM ASSY,	1.00	87.90		87.90
39	7	U75442-47080 PLATE, BACK DOOR	1.00	87.90		87.90
40	8	U75441-47130 PLATE, LUGGAGE COMPT	1.00	75.70		75.70
41	9	U81561-47252 LENS & BODY, RR	1.00	1022.70		1022.70
42	0	U81551-47262 LENS & BODY, RR	1.00	1069.50		1069.50
43	1	U81551-47262 LENS & BODY, RR	1.00	1069.50		1069.50
44	2	T81496-21010 GUIDE, RR	2.00	5.00		10.00
45	3	U89997-30070 ANTENNA, ELECTRICAL	1.00	266.20		266.20
46	4	T21000-20 SIKA 182010 SIKA TACK GO! (BLA	2.00	108.00		216.00
47	5	T21000-22 SIKA 207. G+P ADHESIVE PRIMER	1.00	200.00		200.00

For & on behalf of Borneo Motors (Singapore) Pte Ltd	Customer's Signature	Charge Summary	Total 25,145.35
	Please acknowledge receipt of vehicle	Parts 15,326.55 Labour 9,718.00 Sublet 100.80 Lubrication/Fluid 0.00 Others 0.00	GST 9.00% 2,263.08
			Less 0.00 Amount Due 27,408.43

Company Copy