

SPEEDWERKZ PRIVATE LIMITED
1 KAKI BUKIT AVENUE 6 #01-73, AUTOBAY, SINGAPORE 417883
Tel: 96195936 / info@speedwerkz.biz

not Allowed
 LKK
 mo: 045
 2/8/24
 2/5 & 2200
 the price of the car
 3 days

VEHICLE NUMBER: GBA5793H
 MAKE & MODEL: TOYOTA DYNA

FRONT SIDE MIRROR	garnish LH	one	\$341.30	✓
FRONT SIDE MIRROR BRACKET LH	11		\$145.70	X
FRONT SIDE MIRROR LH	11		\$322.60	X
FRONT CENTRE BLACK GARNISH LH	one		\$187.20	✓
FRONT CORNER PANEL LH	DD		\$396.10	✓
FRONT GRILLE	11		\$809.10	X
FRONT GRILLE LOGO	11		\$70.80	X
FRONT CENTRE PANEL	R		\$1,619.90	X
HEADLAMP LH	one		\$1,247.80	✓
FRONT BUMPER	11		\$748.90	X
FRONT BUMPER BRACKET LH	11		\$160.00	X
AIRCON CONDENSOR LH	11		\$1,827.00	X
FRONT DOOR ASSY LH	11		\$1,784.70	X
FRONT DOOR WINDOW GLASS MOULDING LH	11		\$211.20	X
FRONT DOOR HINGES LH X2	11		\$158.00	X
FRONT DOOR CHECKER LH	11		\$65.00	X
FRONT STEP GARNISH LH	11		\$321.10	X
			\$10,416.40	
			Less 25%	\$2,604.10
			\$7,812.30	
FRONT CENTRE BLACK GARNISH LH CLIPS	11		\$40.00	X
FRONT CORNER PANEL LH CLIPS	11		\$40.00	X
FRONT GRILLE CLIPS	11		\$40.00	X
FRONT DOOR TRIMBOARD LH	11		\$60.00	X
FRONT DOOR COMPANY STICKER LH	11		\$70.00	X
FRONT DOOR WINDOW VISOR SET	11		\$200.00	X
			\$450.00	
TO CHECK FRONT WIRING & HEADLAMP LEVELING			\$60.00	20
TO REPLACE CONDENSER LH AND RECHARGE AC GAS	11		\$160.00	X
TO REMOVE AND TRANSFER FRONT LH DOOR FITTINGS	11		\$120.00	X
TO CONDUCT WHEEL ALIGNMENT	11		\$120.00	X
TO PROVIDE LABOUR, WORKMANSHIP			\$1,000.00	500
TO SPRAY PAINT ON AFFECTED PANELS			\$1,000.00	600
RUST PROOFING	11		\$120.00	X
			\$2,580.00	
			\$10,842.30	

Total

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) to the resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

2-21724
 252
 1628.30
 40
 1120
 2788.3
 202
 1231