



ZOOM AUTOWERKS PTE LTD

130 Bedok Reservoir Road
#08-1339 Singapore 470130
Tel: 9450 7920
* zoomautowerks@gmail.com

Not Authorised

5 August 2024

REG NO.: SKK 633 K
MAKE/MODEL: MINI ONE

du
moray
2/8/24
2/5 @ 4100 | 4 days

ESTIMATED REPAIR COST FOR THE VEHICLE MENTIONED ABOVE

QTY	DESCRIPTION	AMT(\$)
<u>LIST ITEMS</u>		
1	Front bonnet	\$ 1,150.00 ✓
1 set	Front bonnet strip sticker new	\$ 296.00 ✓
1	Front bonnet lock	\$ 145.00 X
1	Front bonnet side arch garnish	\$ 255.00 X
1	Front headlamp -RH	\$ 1,455.00 ✓
1	Front headlamp chrome rim	\$ 285.00 ✓
1	Front grille assy	\$ 425.00 X
1	Front bumper	\$ 855.00 ✓
1	Front bumper fog lamp	\$ 255.00 X
1	Front bumper fog lamp cover	\$ 125.00 X
1	Front bumper side retainer	\$ 58.00 X
1	Front fender -RH	\$ 535.00 X
1	Front fender outer protector RH	\$ 165.00 ✓
1	Front fender emblem	\$ 98.00 X
1	Front wheel rim	\$ 1,020.00 X
1	Front wheel hub with bearing	\$ 620.00 X
1	Front shock absorber	\$ 750.00 X
1	Front knuckle arm	\$ 580.00 X
1	Front lower arm	\$ 520.00 X
		\$ 9,592.00
	Less 5%	\$ 479.60
		\$ 9,112.40

SPECIAL NETT ITEMS

1	Front bumper clip (1 set)	\$ 80.00 40
1	Front fender inner shield clip (1 set)	\$ 50.00 X
1	Front tyre	\$ 450.00 X
		\$ 580.00

LABOUR CHARGES

1	To check wiring and reset headlamps focusing.	\$ 80.00 20
2	To remove and refit front undercarriage.	\$ 250.00 X
3	To conduct wheel alignment.	\$ 150.00 X
4	To apply undercoating.	\$ 100.00 40
5	Panel beating.	\$ 1,300.00 400
6	To re-spray painting on the affected areas.	\$ 1,200.00 650
		\$ 3,080.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

GRAND TOTAL :

Page 1 of 1

Acknowledged by Repairer

Signature:

Date:

\$ 12,772.40

p 4206
52
3995.70
40
1110
5146.7
4116.